

Pre-Demolition Asbestos Survey Report
for
The McCurdy's Building
of
Midtown Plaza Complex
Rochester, New York



Prepared for:



Upstate Empire State Development Corp.
400 Andrews Street, Suite 100
Rochester, New York 14604

Prepared by:



LiRo Engineers, Inc.

690 Delaware Avenue
Buffalo, New York 14209

FINAL
December 17, 2008



Report of Asbestos Survey Services

TABLE OF CONTENTS

	Page
1.0 Executive Summary	1
2.0 Field Survey Procedures and Sample Analysis Methods.....	3
3.0 Inspection Scope and Material Assessment Results.....	5
4.0 Conclusions and Recommendations	8

Appendices

Appendix A: Bulk Sample Field Data Sheets with Chain of Custody & Laboratory Results

Appendix B: Laboratory Accreditations and Personnel Certifications

Appendix C: Bulk Sample Location Drawings

Appendix D: Photographic Log

Appendix E: Sear-Brown 1992 Friable Asbestos Investigation Reports



Report of Asbestos Survey Services

1.0 EXECUTIVE SUMMARY

LiRo Engineers, Inc. was retained to prepare an asbestos survey for pre-demolition purposes at the McCurdy's Building (vacant commercial office building, department store and additions). JMD Environmental, Inc. conducted the field sampling on behalf of LiRo and collaborated with LiRo in preparation of this asbestos survey report. Field work related to the survey was conducted during May and August 2008. Supplemental sampling was conducted during November and December 2008. In total, two hundred (200) samples were collected for asbestos analysis from the area. Samples were analyzed by EMSL Analytical (Job # 81-21-104) or AmeriSci Richmond (Job #108051631). Analytical results are included in Appendix A of this report. This report represents Site conditions as of December 2008.

Figure 1 illustrates the location of the McCurdy Building in relation to the rest of the Midtown Plaza.

The McCurdy's Building consists of a sub-basement, basement and 6 floors totaling approximately 494,700 square feet of floor space. Additionally, limited bulk sampling was performed on the Main Street Skywalk as part of this survey. However, due to the skywalks shared use with an adjacent building, JMD was unable to implement the destructive sampling necessary to thoroughly characterize the skywalk, therefore, following review of structural drawings, assumptions were made in determining the presence of asbestos containing materials related to the skywalk.

The purpose of the survey was to determine the presence, location and condition of ACM (asbestos containing materials) within the described scope of work at the above referenced location. This survey includes the following:

- Identification of suspect asbestos containing materials.
- Sampling and analysis of suspect materials.
- Identification of the location, approximate quantity, friability and condition of confirmed asbestos containing materials.

Areas of the building have been separated into sections (1, 2, 3 and 4) based on the original building footprint and each subsequent addition. These sections were later used in asbestos management plan reports and then again in this report. The locations of building sections 1-4 are illustrated on Figure 2.

Information from a previous Friable Asbestos Containing Building Materials Survey performed by The Sear-Brown Group, Inc. (Sear-Brown) dated June 1992 and a Phase I Environmental Review prepared by Sear-Brown dated June 1992 has been incorporated into this report. The Sear-Brown asbestos survey report and the section of the Phase I report discussing asbestos containing materials are attached as Appendix E to this report.

Analytical results of bulk samples collected indicate the following materials **contain asbestos** (greater than 1-percent).



Report of Asbestos Survey Services

- Spray-on Fireproofing – 417,500 SF
- Ceiling systems – 262,750 SF
- Pipe insulation – 6,990 LF
- Pipe insulation debris – 100 SF
- Fittings on fiberglass pipe insulation – 670 fittings
- Duct/duct block insulation – 2,550 SF
- Floor tile/mastic – 39,700 SF
- Terrazzo tar paper - 82,500 SF
- Mirror mastic – 12,030 SF
- Transite panels/boards – 2,820 SF
- Transite electrical panel – 9 panel boxes
- Fire doors – 44 doors
- Vibration cloth/expansion joints – 48 each
- Caulk at walk-in cooler – 20 SF
- Windows with ACM caulk/glaze – 34 each
- Mastic from 1x1 ceiling tiles – 4,500 SF
- Transite cooling tower – 20'x20'x15', plus 100 SF of spare transite replacement panels
- Roof flashing – 5,250 LF
- Roof vents - 3 vents
- Coping tar – 500 LF
- Transite pipe – 40 LF
- Elevator components – 7 each



Report of Asbestos Survey Services

2.0 FIELD SURVEY PROCEDURES AND SAMPLE ANALYSIS METHODS

Guidelines used for the inspection were established by the Environmental Protection Agency (EPA) in the Guidance for Controlling Asbestos Containing Materials in Buildings, Office of Pesticides and Toxic Substances, Doc 560/5-85-024, and 40 CFR Part 763, Asbestos Hazard Emergency Response Act (AHERA).

Field information was organized in accordance with the AHERA methodology of homogenous area (HA). During the survey, reasonable effort was made to identify all locations and types of ACM materials associated with the scope of work. Sampling has included multiple samples of the same materials chosen at random. However, due to inconsistencies of a manufacturer's processes and the contractor's installation methods, materials of similar construction may contain various amounts of asbestos. Furthermore, some materials that were not originally specified to contain asbestos may in fact contain this mineral. For example, cementitious pipe insulation and plaster were frequently mixed with asbestos at the construction site for ease of application. Locating all asbestos materials can only be definitively achieved by conducting exploratory demolition and sampling every section of pipe insulation, fitting or valve covering, fireproofing, and other suspect ACM.

Bulk samples of suspect ACM were analyzed using polarized light microscopy (PLM) coupled with dispersion staining, as described in 40 CFR Part 763 and the National Emissions Standard for Hazardous Air Pollutants (NESHAPS). NESHAPS is the standard industry protocol for the determination of asbestos in building materials. A suspect material is immersed in a solution of known refractive index and subjected to illumination by polarized light. The color displays that result are compared to a standardized atlas whereby the specific variety of asbestos is determined. It should also be recognized that PLM is primarily a qualitative identification method whereby asbestos percentage, if any, is estimated. While EPA and New York State regulations governing ACM consider materials containing greater than 1-percent as asbestos, accurately quantifying asbestos content below 5-percent has been shown to be unreliable.

The New York State Department of Health has revised the PLM Stratified Point Counting Method. The new method, "Polarized Light Microscopy Methods for Identifying and Quantifying Asbestos in Bulk Samples" can be found as item 198.1 in the Environmental Laboratory Approval program (ELAP) Certification manual. The method specifies a procedure of analysis for bulk samples that fall into the category of "Non-friable Organically Bound" (NOB). This category includes any sample in a flexible to rigid asphalt or vinyl matrix (floor tiles, mastic, roofing shingles, roofing felt, etc.). Additional materials that may fall into this category are textured paints and stucco, pipe valve and joint packing, and a variety of other applications. These samples must be "ashed" in a muffle furnace at 480-degrees Celsius (to remove organic matrix), treated with acid (to remove any mineral carbonate), and filtered through a 0.4-micron filter before being analyzed by PLM. The sample must be weighted between each of these steps to track the percent loss of organic matrix.

ELAP has determined that analysis of NOB materials is not reliably performed by PLM. Therefore, if PLM yields results of 1-percent asbestos or less, the result must be confirmed by TEM. Bulk



Report of Asbestos Survey Services

samples that undergo TEM analysis use the sample reduction methodology stated above for NOB analysis by PLM. ELAP certified laboratories must include the following statement with their PLM analysis results for each “negative” (1-percent or less asbestos) NOB sample: “Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Before this material can be considered or treated as non-ACM, confirmation must be made by quantitative transmission electron microscopy”.

All samples were initially analyzed by Polarized Light Microscopy. Samples which yielded a negative PLM result and which are classified as a "non-friable" material, were then re-analyzed utilizing Transmission Electron Microscopy methodology described above. Sample analysis was performed by Amerisci Richmond located at 13635 Genito Road, Midlothian, Virginia and EMSL Analytical, Inc. located at 490 Rowley Road, Depew, New York. Laboratory accreditations are listed below:

Amerisci Richmond

- National Voluntary Laboratory Accreditation Program (Lab Code 101904-0)
- New York State Environmental Laboratory Approval Program (Lab ID No. 10984)

EMSL Analytical

- National Voluntary Laboratory Accreditation Program (Lab Code 200056-0)
- New York State Environmental Laboratory Approval Program (Lab ID No. 11606)



Report of Asbestos Survey Services

3.0 INSPECTION SCOPE AND MATERIAL ASSESSMENT RESULTS

The intent of this survey was to locate and identify asbestos containing materials located throughout the building in order to schedule its removal in anticipation of site demolition.

The following suspect materials were sampled and analyzed for asbestos content. Materials listed in **BOLD PRINT** were determined to be asbestos containing. Analytical data is included in Appendix A of this report. Sample locations are illustrated on the bulk sample location figures included as Appendix C of this report. A photographic log is included as Appendix D.

Homogeneous Material	Sample #'s	Reference Figure	ACM	Friability
Spray-on Fireproofing	Previously reported by Sear-Brown		Y	Friable
Pipe Insulation	Previously reported by Sear-Brown		Y	Friable
Fittings on fiberglass pipe insulation	Previously reported by Sear-Brown		Y	Friable
Gray 9x9 Floor tile + mastic	MC-01, 02	BSL-7,8	N	-
Red linoleum flooring	MC-03, 04	BSL-8	N	-
12x12 Pink floor tile + mastic	MC-05, 06	BSL-6	N	-
Window sill mastic (interior)	MC-07, 08	BSL-8	N	-
Mastic on 1x1 ceiling tiles (brown)	MC-09, 10	BSL-8	Y	Non-friable
Floor leveler + carpet mastic	MC-11, 12	BSL-6	N	-
Mastic under computer floor posts	MC-13, 14	BSL-6	N	-
Original window glaze	MC-15, 16	BSL-6	Y	Non-friable
Mastic on vinyl cove base	MC-17, 18	BSL-8	N	-
Paper tabs on ceiling (inner floor)	MC-19, 20	BSL-8	N	-
Vermiculite plaster on structural steel	MC-21, 22, 23	BSL-8	N	-
Duct insulation (canvas wrapped)	MC-24, 25, 26	BSL-6	N	-
Tar/foil wrapped fiberglass pipe insulation	MC-27, 28, 29	BSL-7,8	N	-
Drywall compound	MC-33, 34, 35	BSL-6,7,8	N	-
Drywall compound	MC-36, 37, 38	BSL-6,7,8	N	-
Drywall compound	MC-39, 40, 41	BSL-6,7,8	N	-
White duct seam tape	MC-42, 43	BSL-8	N	-
Fireproofing at escalator (new)	MC-44, 45, 46	BSL-7	N	-
Tar/waterproof membrane	MC-47, 48	BSL-8	N	-
1x1 Ceiling tile	MC-49, 50	BSL-2,4	N	-



Report of Asbestos Survey Services

Homogeneous Material	Sample #'s	Reference Figure	ACM	Friability
Gray duct sealant/caulk	MC-51, 52	BSL-5	N	-
Red 12x12 floor tile + mastic	MC-53, 54	BSL-4	Y	Non-friable
Exterior waterproofing tar on foundation	MC-55, 56	BSL-2	N	-
Red kitchen flooring	MC-57, 58	BSL-2	N	-
Red duct caulk	MC-59, 60	BSL-2	N	-
12x12 Gray floor tile + mastic	MC-61, 62	BSL-2	N	-
18"x36" Ceiling tile	MC-63, 64	BSL-5	N	-
12x12 Tan floor tile + mastic	MC-65, 66	BSL-5	Y	Non-friable
Mastic on vinyl cove base	MC-67, 68	BSL-5	N	-
Floor leveler + carpet mastic	MC-69, 70	BSL-5	N	-
Brown battleship linoleum	MC-71, 72	BSL-1	N	-
Mirror mastic	MC-73, 74	BSL-5	Y	Non-friable
Canvas duct insulation	MC-75, 76, 77	BSL-2	N	-
Canvas duct insulation	MC-78, 79, 80	BSL-5	N	-
Cork/tar insulation	MC-81, 82	BSL-2	N	-
Tan 9x9 floor tile + mastic	MC-83, 84	BSL-1	Y	Non-friable
Mastic on vinyl cove	MC-85, 86	BSL-4	N	-
Vapor barrier under terrazzo flooring	MC-87, 88	BSL-3	Y	Non-friable
Terrazzo flooring	MC-89, 90	BSL-3	N	-
Drywall / compound	MC-91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105 MM-274, 275, 276, 277	BSL-2,3,4,5	N	-
Duct Insulation	MC-106, 107, 108	BSL-1,2	Y	Friable
Beige 12x12 Floor tile + mastic	MC-109, 110	BSL-4	N	-
Caulk/sealant at walk-in cooler	MC-111, 112	BSL-2	Y	Non-friable
Gray 12x12 floor tile + mastic	MC-113, 114	BSL-2	N	-
Tar/foil wrapped fiberglass pipe insulation	MC-115, 116, 117	BSL-2,3,5	N	-
Window caulk (interior)	MC-118, 119	BSL-4	Y	Non-friable



Report of Asbestos Survey Services

Homogeneous Material	Sample #'s	Reference Figure	ACM	Friability
Vermiculite plaster on beams	MC-120, 121, 122	BSL-4,8	N	-
Black mirror mastic	MC-123, 124	BSL-3	Y	Non-friable
Tan wall mastic/caulk	MC-125, 126	BSL-3	N	-
Ceiling plaster	MC-127, 128, 129	BSL-3	N	-
Vermiculite plaster on structural columns	MC-130, 131, 132	BSL-3	N	-
Original plaster	MC-133 – 139	BSL-3,4,5,6,7,8	N	-
Plaster	MC-140 – 146	BSL-2,3,4,5,6,7,8	N	-
Plaster at columns	MC-147, 148, 149	BSL-6	N	-
Duct insulation blocks	MC-150	BSL-2	Y	Friable
Int/ext overhang plaster	MC-151, 152, 153	BSL-3	N	-
Int/ext overhang plaster	MC-154, 155, 156	BSL-3	N	-
Int/ext overhang plaster	MC-157, 158, 159	BSL-3	N	-
Green linoleum*	MC-160FL, 161FL	BSL-4	N	-
Paper insulated metal ceiling tiles*	MC-162CT, 163CT	BSL-2,4	N	-
Roof field (Bldg/Roof A)	MC-160, 161	BSL-9	N	-
Flashing (Bldg/Roof A)	MC-162, 163	BSL-9	Y	Non-friable
Roof field (Bldg/Roof B)	MC-164, 165	BSL-9	N	-
Flashing (Bldg/Roof B)	MC-166, 167	BSL-9	Y	Non-friable
Roof field (Bldg/Roof C)	MC-168, 169	BSL-9	N	-
Flashing (Bldg/Roof C)	MC-170, 171	BSL-9	Y	Non-friable
Coping tar	MC-172	BSL-9	Y	Non-friable
Spray-on fireproofing	MC-173, 174	BSL-9	Y	Friable
Caulk b/w exterior blue marble panels	ME-05, 06	BSL-3	N	-
Ext. caulk – marble to sidewalk	ME-09	BSL-3	N	-
Skywalk plaster	SW-7,8,9	BSL-10	N	-
Skywalk stucco	SW-10,11,12	BSL-10	N	-
Skywalk exterior panel caulk	SW-13	BSL-10	N	-
Skywalk roofing	SW-14,15	BSL-10	N	-
Boiler door rope gasket	M-G01A, B	BSL-1	N	-
Exterior louver caulk	MC-EC01A, B	BSL-6	N	-
Exterior window caulk	MC-EC02A, B	BSL-7	N	-



Report of Asbestos Survey Services

4.0 CONCLUSIONS AND RECOMMENDATIONS

Various types of ACM materials have been identified in our survey. These materials, reported in Section 3.0 of this report, will require complete abatement in accordance with applicable codes, rules and regulations prior to the start of the proposed demolition activities. The following table summarizes ACM locations, quantities and conditions as of the time of this survey.

Location/Area	Asbestos Containing Material	Approximate Quantity	Condition
Sub Basement	Pipe Insulation	1,800 LF	Poor
	Pipe Insulation debris	100 SF	Poor
	Fittings on fiberglass pipe insulation	380 each	Poor
	Duct insulation	850 SF	Poor
	Floor tile/mastic	200 SF	Poor
	Expansion gaskets/vibration cloth	12 each	Poor
	Ceiling systems	300 SF	Poor
	Fire doors	6 doors	Fair
	Floor tiles (surplus)	1 box	Fair
	Transite electrical panel boxes	9 each	Fair
	Spray on fireproofing	3,000 SF	Fair
Basement	Pipe Insulation	1,300 LF	Poor
	Fittings on fiberglass pipe insulation	290 fittings	Poor
	Spray-on fireproofing	35,500 SF	Poor
	Ceiling systems	16,500 SF	Poor
	Duct insulation blocks	1,500 SF	Poor
	Terrazzo tar paper	16,500 SF	Fair
	Transite ceiling panels	700 SF	Poor
	Mirror mastic	300 SF	Fair
	Fire doors	6 doors	Fair
	Floor tiles/mastic	17,000 SF	Fair
	Duct insulation	200 SF	Poor
	Transite boards	20 SF	Fair
	Vibration cloth	8 each	Fair
	Caulk at walk-in Coolers	<20 SF	Poor



Report of Asbestos Survey Services

Location/Area	Asbestos Containing Material	Approximate Quantity	Condition
1 st Floor	Spray-on fireproofing	105,140 SF	Poor
	Ceiling systems	47,350 SF	Fair
	Pipe Insulation	400 LF	Poor
	Terrazzo tar paper	66,000 SF	Fair
	Transite boards	1,100 SF	Fair
	Mirror mastic	3,800 SF	Fair
	Vibration cloth	6 each	Fair
	Fire doors	10 doors	Fair
	Roof flashing	800 LF	Fair
2 nd Floor	Spray-on fireproofing	61,800 SF	Fair
	Ceiling systems	41,100 SF	Fair
	Pipe Insulation	600 LF	Fair
	Floor tile/mastic	4,500 SF	Fair
	Windows	12 each	Fair
	Mirror mastic	3,680 SF	Fair
	Vibration cloth	6 each	Fair
	Fire doors	6 doors	Fair
3 rd Floor	Spray-on fireproofing	61,800 SF	Fair
	Ceiling systems	44,600 SF	Fair
	Pipe Insulation	340 LF	Fair
	Floor tile/mastic	18,000 SF	Fair
	Transite boards	1,000 SF	Fair
	Windows	12 each	Fair
	Mirror mastic	2,400 SF	Fair
	Vibration cloth	4 each	Fair
	Fire doors	4 doors	Fair
4 th Floor	Spray-on fireproofing	31,060 SF	Fair
	Ceiling systems	29,300 SF	Fair
	Pipe Insulation	750 LF	Fair
	Windows	4 each	Fair
	Mirror mastic	650 SF	Fair
	Vibration cloth	4 each	Fair
	Fire doors	4 each	Fair



Report of Asbestos Survey Services

Location/Area	Asbestos Containing Material	Approximate Quantity	Condition
5 th Floor	Spray-on fireproofing	59,600 SF	Fair
	Ceiling systems	41,800 SF	Fair
	Pipe Insulation	900 LF	Fair
	Mirror mastic	600 SF	Fair
	Vibration cloth	4 each	Fair
	Fire doors	4 doors	Fair
6 th Floor	Spray-on fireproofing	59,600 SF	Fair
	Ceiling systems	41,800 SF	Fair
	Pipe Insulation	900 LF	Fair
	Windows	8 each	Fair
	Mirror mastic	600 SF	Fair
	Vibration cloth	4 each	Fair
	Fire doors	4 doors	Fair
	Mastic from 1x1 ceiling tiles	4,500 SF	Fair
Roof areas	Transite cooling tower	20'x20'x15'	Fair
	Roof flashing	4,450 LF	Fair
	Coping tar	500 SF	Fair
	Transite pipe	40 LF	Fair
	Spare Transite panels for cooling tower	100 SF	Fair
	Roof vents	3 vents	Fair
	Elevator components	7 each	Fair

NOTES:

1. Varying sizes of structural steel members and overspray were taken into consideration when quantifying the spray-on fireproofing. All materials above, and including suspended and fixed ceiling systems where there is fireproofing or asbestos pipe insulation above are to be considered contaminated by asbestos containing debris.
2. Fixed plaster ceilings in Section 1 of this building have ACM pipe insulation above and debris is noted in all areas. This plaster ceiling system is to be considered contaminated. See IMG(s) 1618,1624,1581,1620. The plaster ceiling and all suspect ACM found above the ceiling (including pipe insulation) shall be abated as part of the ceiling system.
3. "Encapsulated" fireproofing, primarily found in Section 2, still shows ACM through gaps and holes throughout. All ceiling systems installed below this material should be considered contaminated. See IMG(s) 1611, 1595.
4. Duct insulation blocks (IMG 1655) in the kitchen/bakery area of the basement of this building continue into the loading dock area of the tunnel. The quantity of this material listed above includes the material that extends into the loading dock area of the tunnel.



Report of Asbestos Survey Services

5. All mastic applied to mirrors is to be considered asbestos containing. This includes, but is not limited to mirrors installed in restrooms, store showrooms, dressing room areas and elevator lobbies.
6. Energized wire was not sampled for the presence of asbestos in this building. This material should be treated as asbestos containing until proven otherwise through bulk sampling.
7. Caulking and glazing on original windows (sampled on the interior) in Section 3 was found to contain asbestos. In certain areas these windows have been covered by renovations to the exterior over the years. All original window units in Section 3 should be removed as asbestos containing.
8. Quantities of pipe insulation reported above only include material not associated with areas of spray-on fireproofing and plaster ceilings. Pipe insulation located above the ceiling in areas containing spray-on fire proofing and/or plaster ceilings shall be removed as part of the fireproofing/ceiling system abatement.
9. Ceiling systems include all materials above the drop ceilings/plaster ceilings (interior ceilings and exterior plaster overhang), including the ceilings themselves and any pipe or duct insulation located above them. All materials located above the ceilings should be assumed to be contaminated with ACM.
10. Roof vents have been installed with ACM flashing material and rope gaskets. Roof vents and their associated caulk and flashing should be removed as ACM.



Report of Asbestos Survey Services

APPENDIX A:

BULK SAMPLE FIELD DATA SHEETS WITH CHAIN OF CUSTODY AND LABORATORY RESULTS

140802163

L1R0 Project 08-21-104
JMD Services Project Number
McCuroys

MAY 09
Survey Date

24 HR 48 HR 3DAY
6 Day

all done
Results Due By

Type of Survey and Address
Owner / Agent

Field Sample #	Material Description	Location	Amount	Chd	F/NF
MC-01	gray 9X7 F.T. + MASTIC	Section 3	6th		
02	"	"	5th		
03	Red Limestone Flooring	Section 1	6th		
04	"	Section 1-6th			
05	12X12 Pink F.T. + MASTIC	Section 1-4th			
06	"	Section 4-4th			
07	Window Sill MASTIC Int.	Section 2	6th		
08	"	Section 7	6th		
09	Ceiling Tile Mastic 1X1 Brown	Section 3	6th		
10	"	Section 3	6th		
11	Floor Leveler + Carpet Mastic	Section 1	4th		
12	"	Section 1	4th		
13	Mastic under Composite Floor Panels	Section 1	4th		
14	"	Section 1	4th		
15	Original Window Glaze	Section 3	4th		
MC-16	"	Section 3	4th		

Comments / Special Instructions / Notes:

pos stop per grow

X Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com

5/12/08 D.O. 9:30am

Sampled / Relinquished By

Date and Time

Received By



1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax

140808

Libo PROJECT 08-21-104

JMD Services Project Number

MOTOWN - MCCURDY'S

Type of Survey and Address

Owner / Agent

MAY 08

24 HR 48 HR

Survey Date

Results Du

Number of Samples

Field Sample #	Material Description	Location	Amount	Ch
MC-17	MASTIC ON VINYL CORE BASE	Seal 2	6 th	
18	"	Seal 4	6 th	
19	Paper Tabs on Ceiling Inner Floor	6 th		
20	"	6 th		
21	Vermiculite Plaster on Structural Steel	6 th Seal 1		
22	"	6 th Seal 1		
23	"	6 th Seal 1		
24	Duct Insulation Common Wrap	Seal 3 4 th		
25	"	"	"	
26	"	"	"	
27	TAR/FOIL WRAPPED F.G.P.I.	Seal 3	6 th	
28	"	Seal 1	6 th	
29	"	Seal 3	5 th	
30	Plywood Compound	Seal 3	6 th	
31	"	Seal 3	6 th	
MC-32	"	Seal 3	5 th	

Comments / Special Instructions / Notes:

Pos Stop per group

(X) Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@

JMD

JMD 5/12/08 D.O. 9:30am

Sampled / Relinquished By

Date and Time

Received By

JMD SERVICES

1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-

14080216

Libo Project 08-21-104

JMD Services Project Number

May 08

Survey Date

24 HR 48 HR

6th

Middown - McCurdy's

Type of Survey and Address

Owner / Agent

Number of Samples

Results D

Field Sample #	Material Description	Location	Amount	Cr
MC - 33	Drywall Compound	Sect 2	6	
34	"	Sect 2	5	
35	"	Sect 2	4	
36	Drywall Compound	Sect 4	6th	
37	"	Sect 4	5th	
38	"	Sect 4	4th	
39	Drywall Compound	Sect 1	6th	
40	"	Sect 1	5th	
41	"	Sect 1	4th	
42	White Duct Seam Tape	Section 1	6th	
43	"	Section 1	6th	
44	Fireproofing @ Escalator (New)	Section 3	5th	
45	"	Sect 3	5th	
46	"	Sect 3	5th	
47	TAC/WATERPROOF MANGROVE Floor	Sect 3	6th	
48	"	Sect 3	6th	

Comments / Special Instructions / Notes:

Pos. Stop per group

XJ Analyze PLM then TEM if negative AND NOB

email results to - rbarr276

JWB

JWB 5/12/08 DO 9:30am

Sampled / Relinquished By

Date and Time

Received By

JMD
SERVICES

1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163

EMSL Proj: Midtown
Analysis Date: 5/13/2008
Report Date: 5/19/2008

**Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY
State ELAP 198.6 Method**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-01 140802163-0026	gray 9x9 FT	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-01 140802163-0027	mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-02 140802163-0028	gray 9x9 FT	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-02 140802163-0029	mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-03 140802163-0030	red linoleum flooring	Red	100.0	None	Inconclusive: No Asbestos Detected
MC-04 140802163-0031	red linoleum flooring	Red	100.0	None	Inconclusive: No Asbestos Detected
MC-05 140802163-0032	12x12 pink FT	Pink	100.0	None	Inconclusive: No Asbestos Detected
MC-05 140802163-0033	mastic	Cream	100.0	None	Inconclusive: No Asbestos Detected
MC-06 140802163-0034	12x12 pink FT	Pink	100.0	None	Inconclusive: No Asbestos Detected
MC-06 140802163-0035	mastic	Cream	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Andrew Maciejewski (5)
Rachel Giese (22)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/12/08 9:30 AM
 EMSL Order: 140802163
 EMSL Proj: Midtown
 Analysis Date: 5/13/2008
 Report Date: 5/19/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-07 140802163-0036	window sill mastic int	Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-08 140802163-0037	window sill mastic int	Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-09 140802163-0038	ceiling tile mastic 1x1 brown	Brown	96.9	None	3.1 Chrysotile 3.1 Total All Types
MC-10 140802163-0039	ceiling tile mastic 1x1 brown	Brown			
Not Analyzed Positive stop					
MC-11 140802163-0040	floor leveler & carpet mastic	Tan/Yellow	100.0	None	Inconclusive: No Asbestos Detected
MC-12 140802163-0041	floor leveler & carpet mastic	Tan/Yellow	100.0	None	Inconclusive: No Asbestos Detected
MC-13 140802163-0042	mastic under computer floor posts	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-14 140802163-0043	mastic under computer floor posts	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-15 140802163-0044	original window glaze	Brown	99.5	None	Inconclusive : <1 Chrysotile <1 Total All Types

Analyst(s)

Andrew Maciejewski (5)
 Rachel Giese (22)

Rhonda McGee, Laboratory Manager
 or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method imitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163

EMSL Proj: Midtown
Analysis Date: 5/13/2008
Report Date: 5/19/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-16 140802163-0045	original window glaze	Brown	98.8	None	1.2 Chrysotile 1.2 Total All Types
MC-17 140802163-0046	mastic on vinyl covebase	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-18 140802163-0047	mastic on vinyl covebase	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-27 140802163-0048	tar/foil wrapped F.G.P.I.	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-28 140802163-0049	tar/foil wrapped F.G.P.I.	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-29 140802163-0050	tar/foil wrapped F.G.P.I.	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-47 140802163-0051	tar/waterproofing membrane floor	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-48 140802163-0052	tar/waterproofing membrane floor	Black	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Andrew Maciejewski (5)
Rachel Giese (22)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163

EMSL Proj: Midtown
Analysis Date: 5/17/2008
Report Date: 5/19/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-19 140802163-0001	6th	Brown Fibrous Homogeneous	90.00% Cellulose	10.00% Non-fibrous (other)	None Detected
MC-20 140802163-0002	6th	Brown Fibrous Homogeneous	90.00% Cellulose	10.00% Non-fibrous (other)	None Detected
MC-21 140802163-0003	6th sect 1	Brown Fibrous Homogeneous	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
MC-22 140802163-0004	6th sect 1	Brown Fibrous Homogeneous	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
MC-23 140802163-0005	6th sect 1	Brown Fibrous Homogeneous	7.00% Cellulose	93.00% Non-fibrous (other)	None Detected
MC-24 140802163-0006	sect 3 4th	Gray Fibrous Homogeneous	45.00% Cellulose 45.00% Glass	10.00% Non-fibrous (other)	None Detected
MC-25 140802163-0007	sect 3 4th	Gray Fibrous Homogeneous	40.00% Cellulose 40.00% Glass	20.00% Non-fibrous (other)	None Detected
MC-26 140802163-0008	sect 3 4th	Gray Fibrous Homogeneous	40.00% Cellulose 40.00% Glass	20.00% Non-fibrous (other)	None Detected
MC-30 140802163-0009	sect 3 6th				Not Submitted
MC-31 140802163-0010	sect 3 6th				Not Submitted

Analyst(s)

Andrew Maciejewski (25)
Rachel Giese (5)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/12/08 9:30 AM
 EMSL Order: 140802163

EMSL Proj: Midtown
 Analysis Date: 5/17/2008
 Report Date: 5/19/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
MC-32 140802163-0011	sect 3 5th				Not Submitted
MC-33 140802163-0012	sect 2 6	Gray Fibrous Layer # 1	<1% Glass	100.00% Non-fibrous (other)	None Detected
MC-33 140802163-0012A	joint compound	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-33 140802163-0012B	paper	Brown Fibrous Layer # 3	90.00% Cellulose	10.00% Non-fibrous (other)	None Detected
MC-34 140802163-0013	sect 2 5	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-35 140802163-0014	sect 2 4	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-36 140802163-0015	sect 4 6th	White Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-36 140802163-0015A	(tape) paper	Brown/White Fibrous Layer # 2	90.00% Cellulose	10.00% Non-fibrous (other)	None Detected
MC-37 140802163-0016	sect 4 5th	White Fibrous Layer # 1	20.00% Cellulose	80.00% Non-fibrous (other)	None Detected
MC-37 140802163-0016A	paper	White Fibrous Layer # 2	90.00% Cellulose	10.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (25)
 Rachel Giese (5)

Rhonda McGee, Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163

EMSL Proj: Midtown
Analysis Date: 5/17/2008
Report Date: 5/19/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-38 140802163-0017	sect 4 4th	White Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-38 140802163-0017A	paper	Brown/White Fibrous Layer # 2	60.00% Cellulose	40.00% Non-fibrous (other)	None Detected
MC-39 140802163-0018	sect 1 6th	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-40 140802163-0019	sect 1 5th	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-41 140802163-0020	sect 1 4th	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-42 140802163-0021	section 1 6th	White Fibrous Homogeneous	50.00% Cellulose	50.00% Non-fibrous (other)	None Detected
MC-43 140802163-0022	section 1 6th	White Fibrous Homogeneous	55.00% Cellulose	45.00% Non-fibrous (other)	None Detected
MC-44 140802163-0023	section 3 5th	Gray Fibrous Homogeneous	10.00% Cellulose 1.00% Glass	89.00% Non-fibrous (other)	None Detected
MC-45 140802163-0024	section 3 5th	Gray Fibrous Homogeneous	10.00% Cellulose 2.00% Glass	88.00% Non-fibrous (other)	None Detected
MC-46 140802163-0025	section 3 5th	Gray Fibrous Homogeneous	12.00% Cellulose 1.00% Glass	87.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (25)
Rachel Giese (5)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163

EMSL Proj: Midtown
Analysis Date: 5/15/2008
Report Date: 5/19/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-01 140802163-0026	gray 9x9 FT	Gray	100.0	None	No Asbestos Detected	
MC-01 140802163-0027	mastic	Black	100.0	None	No Asbestos Detected	
MC-02 140802163-0028	gray 9x9 FT	Gray	100.0	None	No Asbestos Detected	
MC-02 140802163-0029	mastic	Black	100.0	None	No Asbestos Detected	
MC-03 140802163-0030	red linoleum flooring	Red	100.0	None	No Asbestos Detected	
MC-04 140802163-0031	red linoleum flooring	Red	100.0	None	No Asbestos Detected	
MC-05 140802163-0032	12x12 pink FT	Pink	100.0	None	No Asbestos Detected	
MC-05 140802163-0033	mastic	Cream	100.0	None	No Asbestos Detected	
MC-06 140802163-0034	12x12 pink FT	Pink	100.0	None	No Asbestos Detected	
MC-06 140802163-0035	mastic	Cream	100.0	None	No Asbestos Detected	

Analyst(s)

Brian Walczak (23)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163
EMSL Proj: Midtown
Analysis Date: 5/15/2008
Report Date: 5/19/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-07 140802163-0036	window sill mastic int	Brown	100.0	None	No Asbestos Detected	
MC-08 140802163-0037	window sill mastic int	Brown	100.0	None	No Asbestos Detected	
MC-11 140802163-0040	floor leveler & carpet mastic	Tan/Yellow	100.0	None	No Asbestos Detected	
MC-12 140802163-0041	floor leveler & carpet mastic	Tan/Yellow	100.0	None	No Asbestos Detected	
MC-13 140802163-0042	mastic under computer floor posts	Black	100.0	None	No Asbestos Detected	
MC-14 140802163-0043	mastic under computer floor posts	Black	100.0	None	No Asbestos Detected	
MC-17 140802163-0046	mastic on vinyl covebase	Black	100.0	None	No Asbestos Detected	
MC-18 140802163-0047	mastic on vinyl covebase	Black	100.0	None	No Asbestos Detected	
MC-27 140802163-0048	tar/foil wrapped F.G.P.I.	Various	100.0	None	No Asbestos Detected	
MC-28 140802163-0049	tar/foil wrapped F.G.P.I.	Various	100.0	None	No Asbestos Detected	

Analyst(s)

Brian Walczak (23)

Rhonda McGee

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO:
Received: 05/12/08 9:30 AM
EMSL Order: 140802163

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 McCurdy's**

EMSL Proj: Midtown
Analysis Date: 5/15/2008
Report Date: 5/19/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-29 140802163-0050	tar/foil wrapped F.G.P.I.	Various	100.0	None	No Asbestos Detected	
MC-47 140802163-0051	tar/waterproofing membrane floor	Black	100.0	None	No Asbestos Detected	
MC-48 140802163-0052	tar/waterproofing membrane floor	Black	100.0	None	No Asbestos Detected	

Analyst(s)

Brian Walczak (23)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

140807305

Life Project # 08-21-104 JMD Services Project Number		1/14/08 Survey Date		24 HR 48 HR 3 DAY Results Due By	
MORTON - McCURRY'S Type of Survey and Address		Owner / Agent		Number of Samples	

Field Sample #	Material Description	Location	Amount	Cnd	F/NF
MC-113	12x12 Gray F.T. + mastic	Sect ①	Basement		
114	"	"			
115	TAR/FIL WRAPPED F.G.P.T.	Sect 3	Basement		
116	"	Sect 4	3 rd Fl		
117	"	Sect 1	1 st Fl		
118	Window Caulk Interior	Sect 3	2 nd Fl		
119	"	"	"		
120	Vermiculite plaster on Beams	Sect 1	3 rd Fl		
121	"	Sect 1	2 nd Fl		
122	"	Sect 1	6 th Fl		
123	Micropore mastic Black	Sect ①	1 st Fl		
124	"	Sect ①	1 st Fl		
125	Tan wall Mastic/Caulk	Sect ①	1 st Fl		
126	"	Sect 1	1 st Fl		
127	Ceiling plaster	Sect 3	1 st Fl		
MC-128	"	"	"		

Comments / Special Instructions / Notes:

Pos stop per group, please.

Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com

15 May 08

15 May 08 5:15:08 6:40 PM

Sampled / Relinquished By

Received By



1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax

140802305

Libro Project # 08-21-104
JMD Services Project Number

MISTOWS - MCKENNEY'S
Type of Survey and Address

Owner / Agent

MAY 08
Survey Date

24 HR 48 HR 3 DAY
6 Day

Number of Samples
Results Due By

Field Sample #	Material Description	Location	Amount	Chd	F/NF
MC-129	Ceiling Plaster	Sect 3	1 st Fl		
130	Vermiculite Plaster on Column	Sect 3	1 st Fl		
131	↓	Sect 3	7 th Fl		
132	↓	Sect 3	1 st above		
133	ORG PLASTER Sect 3	Sect 3	2 nd Fl		
134	↓	Sect 3	2 nd Fl		
135	↓	Sect 3	6 th Fl		
136	↓	Sect 3	5 th Fl		
137	↓	Sect 3	4 th Fl		
138	↓	Sect 3	3 rd Fl		
139	↓	Sect 3	1 st Fl		
140	Plaster Sect. 1		6 th		
141	↓		5 th		
142	↓		4 th		
143	↓		3 rd		
MC-144	↓		3 rd		

Comments / Special Instructions / Notes:

(X) Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com

15 MAY 08

Bjrm DO 5:15:08 6:40 PM

Received By:


Date and Time

Sampled / Relinquished By



1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/15/08 6:40 PM
 EMSL Order: 140802305
 EMSL Proj: Midtown
 Analysis Date: 5/19/2008
 Report Date: 5/22/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-113 140802305-0022	12x12 gray ft	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-113 140802305-0022A	12x12 gray ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-114 140802305-0023	12x12 gray ft	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-114 140802305-0023A	12x12 gray ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-115 140802305-0024	tar/foil wrapped FGPI	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-116 140802305-0025	tar/foil wrapped FGPI	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-117 140802305-0026	tar/foil wrapped FGPI	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-118 140802305-0027	window caulk interior	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-119 140802305-0028	window caulk interior	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-123 140802305-0029	mirror mastic black	Black	78.1	None	21.9 Chrysotile 21.9 Total All Types


Analyst(s)

Brian Walczak (10)
 Tom Hanes (3)

Rhonda McGee, Laboratory Manager
 or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method imitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476

Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802305

EMSL Proj: Midtown
Analysis Date: 5/19/2008
Report Date: 5/22/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-124 140802305-0030	mirror mastic black	Black			
Not Analyzed Positive stop					
MC-125 140802305-0031	tan wall mastic/caulk	Yellow/White	100.0	None	Inconclusive: No Asbestos Detected
MC-126 140802305-0032	tan wall mastic/caulk	Yellow/White	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Brian Walczak (10)

Tom Hanes (3)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method imitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/15/08 6:40 PM
 EMSL Order: 140802305
 EMSL Proj: Midtown
 Analysis Date: 5/21/2008
 Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-120 140802305-0001	sect 1 3rd fl	Gray Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-121 140802305-0002	sect 1 2nd fl	Gray Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-122 140802305-0003	sect 1 6th fl	Gray Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-127 140802305-0004	sect 3 1st fl	Brown Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-127 140802305-0004A	white	White Fibrous Layer # 2	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
MC-128 140802305-0005	sect 3 1st fl	Brown Fibrous Layer # 1	10.00% Cellulose	90.00% Non-fibrous (other)	None Detected
MC-128 140802305-0005A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-129 140802305-0006	sect 3 1st fl	Brown Fibrous Layer # 1	10.00% Cellulose	90.00% Non-fibrous (other)	None Detected
MC-129 140802305-0006A	sect 3 1st fl	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-130 140802305-0007	sect 3 1st fl	Brown Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (28)
 Rachel Giese (6)

Rhonda McGee, Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/15/08 6:40 PM
 EMSL Order: 140802305
 EMSL Proj: Midtown
 Analysis Date: 5/21/2008
 Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-131 140802305-0008	sect 3 1st fl	Brown Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-132 140802305-0009	sect 1 above	Brown Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-133 140802305-0010	sect 3 2nd fl	Gray/White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-134 140802305-0011	sect 3 2nd fl	Brown/White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-135 140802305-0012	sect 3 6th fl	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-135 140802305-0012A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-136 140802305-0013	sect 3 5th fl	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-136 140802305-0013A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-137 140802305-0014	sect 3 4th fl C column	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-137 140802305-0014A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (28)
 Rachel Giese (6)

Rhonda McGee, Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802305

EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-138 140802305-0015	sect 3 3rd fl	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-138 140802305-0015A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-139 140802305-0016	sect 3 1st fl	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-139 140802305-0016A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-140 140802305-0017	6th	Gray Fibrous Layer # 1	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
MC-140 140802305-0017A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-141 140802305-0018	5th	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-141 140802305-0018A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-142 140802305-0019	4th	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-142 140802305-0019A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (28)
Rachel Giese (6)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802305

EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-143 140802305-0020	3rd	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-143 140802305-0020A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-144 140802305-0021	3rd	Brown Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-144 140802305-0021A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (28)
Rachel Giese (6)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802305
EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-113 140802305-0022	12x12 gray ft	Gray	100.0	None	No Asbestos Detected	
MC-113 140802305-0022A	12x12 gray ft mastic	Black	100.0	None	No Asbestos Detected	
MC-114 140802305-0023	12x12 gray ft	Gray	100.0	None	No Asbestos Detected	
MC-114 140802305-0023A	12x12 gray ft mastic	Black	100.0	None	No Asbestos Detected	
MC-115 140802305-0024	tar/foil wrapped FGPI	Various	100.0	None	No Asbestos Detected	
MC-116 140802305-0025	tar/foil wrapped FGPI	Various	100.0	None	No Asbestos Detected	
MC-117 140802305-0026	tar/foil wrapped FGPI	Various	100.0	None	No Asbestos Detected	
MC-118 140802305-0027	window caulk interior	Gray	78.1	None	21.9 Chrysotile	21.9
MC-119 140802305-0028	window caulk interior	Gray				
Not Analyzed Positive stop						

Analyst(s)

Rhonda McGee (11)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802305
EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-125 140802305-0031	tan wall mastic/caulk	Yellow/White	100.0	None	No Asbestos Detected	
MC-126 140802305-0032	tan wall mastic/caulk	Yellow/White	100.0	None	No Asbestos Detected	

Analyst(s)

Rhonda McGee (11)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

1408 02306

Lido Project # 08-21-104
JMD Services Project Number

MCOWAN - McCulloughs
Type of Survey and Address

Owner / Agent

MAY 08
Survey Date

24 HR 48 HR 3 DAY
6 DAY

Number of Samples Results Due By

Field Sample #	Material Description	Location	Amount	Cnd	F/NF
MC-145	Plaster Sect 1				
146	↓	Bakery / Basement			
147	Plaster @ Columns	Sect 3 4th			
148	↓	↓			
149	↓				
MC-150	Duct Insulation Blocks	Sect 1 Basement/Bakery			
151	Int/Ext. overhang Plaster (Brick)	Sect 3 1st Fl.			
152	↓	w/ Argonite			
153	↓				
154	Int/Ext overhang Plaster Rough	Sect 3			
155	↓	↓			
156	↓				
157	Int/Ext overhang Plaster	Sect 4 @ Field			
158	↓	↓			
MC-159	↓				

Comments / Special Instructions / Notes:

Pos Stop per group.

Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com

FWZ


15 MAY

RAW 5:15 08 DO 6:40 PM

Sampled / Relinquished By

Date and Time

Received By

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476

Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802306

EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-145 140802306-0001	1st fl	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-145 140802306-0001A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-146 140802306-0002	bakery/basement	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-146 140802306-0002A	white	White Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-147 140802306-0003	sect 3 4th	White/Gray Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-148 140802306-0004	sect 3 4th	White/Gray Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-149 140802306-0005	sect 3 4th	White/Gray Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-150 140802306-0006	sect 1 basement/bakery	Gray Fibrous Homogeneous		89.00% Non-fibrous (other)	11.00% Amosite
MC-151 140802306-0007	sect 3 1st fl	Gray Fibrous Layer # 1	10.00% Cellulose	90.00% Non-fibrous (other)	None Detected
MC-151 140802306-0007A	plaster	Gray Fibrous Layer # 2	1.00% Cellulose	99.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (19)

Rachel Giese (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/15/08 6:40 PM
 EMSL Order: 140802306
 EMSL Proj: Midtown
 Analysis Date: 5/21/2008
 Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-151 140802306-0007B	paper	White/Gray Fibrous Layer # 3	50.00% Cellulose	50.00% Non-fibrous (other)	None Detected
MC-152 140802306-0008	sect 3 1st fl	White Fibrous Layer # 1	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
MC-152 140802306-0008A	plaster	Gray Non-Fibrous Layer # 2	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
MC-152 140802306-0008B	paper	Brown/White Fibrous Layer # 3	50.00% Cellulose	50.00% Non-fibrous (other)	None Detected
MC-153 140802306-0009	sect 3 1st fl	Gray Non-Fibrous Layer # 1		100.00% Non-fibrous (other)	None Detected
MC-153 140802306-0009A	plaster	Brown Non-Fibrous Layer # 2		100.00% Non-fibrous (other)	None Detected
MC-153 140802306-0009B	paper	Brown Fibrous Layer # 3	50.00% Cellulose	50.00% Non-fibrous (other)	None Detected
MC-154 140802306-0010	sect 3	Gray/White Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-155 140802306-0011	sect 3	Gray/White Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-156 140802306-0012	sect 3	Gray/White Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (19)
 Rachel Giese (4)

Rhonda McGee, Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalotab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802306
EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-157 140802306-0013	sect 4 @ exit	Gray/White Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-158 140802306-0014	sect 4 @ exit	Gray/White Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected
MC-159 140802306-0015	sect 4 @ exit	Gray/White Non-Fibrous Heterogeneous		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (19)
Rachel Giese (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11608

140802307

LiRo Project # 08-21-104

JMD Services Project Number

MOTOWN - M'CURRY'S

Type of Survey and Address

Owner / Agent

May 08

Survey Date

24 HR 48 HR 3 DAY

6 Day

Number of Samples

Results Due By

Field Sample #	Material Description	Location	Amount	End	F/NF
MC-49	1 X 1 Ceiling tile	Section 3	2° Fl		
50	"	Section 1	Basement		
51	Gray Quot Sealant/Caulk	Section 1	3° Fl		
52	"	"	"		
53	Red 12X12 FT + MSTR	Section 1	2° Fl		
54	Red 12X12 FT + MSTR	Section 1	2° Fl		
55	Exterior Waterproofing in Foundation	Section 3	Basement		
56	"	"	"		
57	Red Kitchen Flooring	Section 1	Basement		
58	"	"	"		
59	Red Quot Caulk	Section 3	Basement		
60	"	"	"		
61	12X12 Gray FT (Aisle tile)	Section 1	2° Fl		
62	"	"	"		
63	18" X 36" Ceiling tile	Section 3	3° Fl		
MC-64	"	"	"		

Comments / Special Instructions / Notes:

Pos steel per group

X Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com



15 May

Barr DO 5:15-08 6:40 PM

Sampled / Relinquished By

Date and Time

Received By:

JMD
SERVICES

1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax

140802307

LiRo Project # 08-21-104

JMD Services Project Number

MICHAEL - MCCORMY'S

Type of Survey and Address

Owner / Agent

MAY 08
Survey Date

24 HR 48 HR 3 DAY
6 DAY

Number of Samples Results Due By

Field Sample #	Material Description	Location	Amount	Cnd	F/NF
MC- 65	2X12 TAN FT + MASTIC	Section ①	3 rd e Selva		
66	"	"	"		
67	MASTIC ON VINYL CARPET MANDIBLE	Section ③	3 rd FL		
68	"	"	"		
69	FLOOR LEVAGE + CARPET MASTIC	Section ③	3 rd FL		
70	"	②			
71	Brown Battleship Linoleum	Sub Basement	Section ①		
72	"	"			
73	MASTIC ON MUDROCK	Section 4	3 rd		
74	"	"	"		
75	Canvas Duct Insulation	Section 3	Basement		
76	"	"	"		
77	"	"	"		
78	Canvas Duct Insulation	Section ①	3 rd FL		
79	"	"	"		
MC- 80	"	Section ④	3 rd FL		

Comments / Special Instructions / Notes:

Pos. stop per group

Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com

For


15 MAY

BK DO 5:15:08 6:40 AM

Sampled / Relinquished By

Date and Time

Received By

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030

Fax: (716) 651-0394

Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307
EMSL Proj: Midtown
Analysis Date: 5/19/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY
State ELAP 198.6 Method**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-51 140802307-0013	gray duct sealant/caulk	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-52 140802307-0014	gray duct sealant/caulk	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-53 140802307-0015	red 12x12 ft	Red	97.2	None	2.8 Chrysotile 2.8 Total All Types
MC-53 140802307-0016	red 12x12 ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-54 140802307-0017	red 12x12 ft	Red			
Not Analyzed Positive stop					
MC-54 140802307-0018	red 12x12 mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-55 140802307-0019	exterior waterproofing in foundation	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-56 140802307-0020	exterior waterproofing in foundation	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-59 140802307-0021	red duct caulk	Brown	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Brian Walczak (15)
Tom Hanes (9)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307

EMSL Proj: Midtown
Analysis Date: 5/19/2008
Report Date: 5/22/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-60 140802307-0022	red duct caulk	Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-61 140802307-0023	12x12 gray ft (aisle tile)	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-62 140802307-0024	12x12 gray ft (aisle tile)	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-65 140802307-0025	12x12 tan ft	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-65 140802307-0026	12x12 tan ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-66 140802307-0027	12x12 tan ft	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-66 140802307-0028	12x12 tan ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-67 140802307-0029	mastic on vinyl cove molding	Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-68 140802307-0030	mastic on vinyl cove molding	Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-69 140802307-0031	floor leveler & carpet mastic	Various	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Brian Walczak (15)
Tom Hanes (9)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307
EMSL Proj: Midtown
Analysis Date: 5/19/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY
State ELAP 198.6 Method**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-70 140802307-0032	floor leveler & carpet mastic	Yellow/White	100.0	None	Inconclusive: No Asbestos Detected
MC-71 140802307-0033	brown battleship linoleum	Brown	99.2	None	Inconclusive : <1 Chrysotile <1 Total All Types
MC-72 140802307-0034	brown battleship linoleum	Brown	99.8	None	Inconclusive : <1 Chrysotile <1 Total All Types
MC-73 140802307-0035	mastic on mirrors	Black	93.9	None	6.1 Chrysotile 6.1 Total All Types
MC-74 140802307-0036	mastic on mirrors	Black			
Not Analyzed Positive stop					

Analyst(s)

Brian Walczak (15)
Tom Hanes (9)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method imitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
 Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
 Customer PO:
 Received: 05/15/08 6:50 PM
 EMSL Order: 140802307

EMSL Proj: Midtown
 Analysis Date: 5/21/2008
 Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-49 140802307-0001	section 3 2nd fl	Gray Fibrous Homogeneous	50.00% Glass	50.00% Non-fibrous (other)	None Detected
MC-50 140802307-0002	section 1 basement	Gray Fibrous Homogeneous	70.00% Glass	30.00% Non-fibrous (other)	None Detected
MC-57 140802307-0003	section 1 basement	Red Fibrous Homogeneous	30.00% Cellulose	69.25% Non-fibrous (other)	0.75% Chrysotile
MC-58 140802307-0004	section 1 basement	Red Fibrous Homogeneous	25.00% Cellulose	74.25% Non-fibrous (other)	0.75% Chrysotile
MC-63 140802307-0005	section 3 3rd	Brown Fibrous Homogeneous	80.00% Cellulose	20.00% Non-fibrous (other)	None Detected
MC-64 140802307-0006	section 3 3rd	Brown Fibrous Homogeneous	95.00% Cellulose	5.00% Non-fibrous (other)	None Detected
MC-75 140802307-0007	sect 3 basement	Tan Fibrous Homogeneous	95.00% Cellulose	5.00% Non-fibrous (other)	None Detected
MC-76 140802307-0008	sect 3 basement	Tan Fibrous Homogeneous	95.00% Cellulose	5.00% Non-fibrous (other)	None Detected
MC-77 140802307-0009	sect 3 basement	Yellow Fibrous Homogeneous	95.00% Cellulose	5.00% Non-fibrous (other)	None Detected
MC-78 140802307-0010	section 1 3rd fl	Yellow Fibrous Homogeneous	30.00% Cellulose 45.00% Glass	25.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (8)
 Rachel Giese (4)

Rhonda McGee, Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307

EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-79 140802307-0011	section 1 3rd fl	Yellow	5.00% Cellulose	10.00% Non-fibrous (other)	None Detected
		Fibrous	85.00% Glass		
		Homogeneous			
MC-80 140802307-0012	section 4 3rd fl	Yellow	70.00% Cellulose	10.00% Non-fibrous (other)	None Detected
		Fibrous	20.00% Glass		
		Homogeneous			

Analyst(s)

Andrew Maciejewski (8)
Rachel Giese (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307
EMSL Proj: Midtown
Analysis Date: 5/22/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-51 140802307-0013	gray duct sealant/caulk	Gray	100.0	None	No Asbestos Detected	
MC-52 140802307-0014	gray duct sealant/caulk	Gray	100.0	None	No Asbestos Detected	
MC-53 140802307-0016	red 12x12 ft mastic	Black	97.7	None	2.3% Chrysotile	2.3
MC-54 140802307-0018	red 12x12 mastic	Black				
Not Analyzed Positive stop						
MC-55 140802307-0019	exterior waterproofing in foundation	Black	100.0	None	No Asbestos Detected	
MC-56 140802307-0020	exterior waterproofing in foundation	Black	100.0	None	No Asbestos Detected	
MC-59 140802307-0021	red duct caulk	Brown	100.0	None	No Asbestos Detected	
MC-60 140802307-0022	red duct caulk	Brown	100.0	None	No Asbestos Detected	
MC-61 140802307-0023	12x12 gray ft (aisle tile)	Gray	100.0	None	No Asbestos Detected	

Analyst(s)

Rhonda McGee (20)

Rhonda McGee

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307

EMSL Proj: Midtown
Analysis Date: 5/22/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-62 140802307-0024	12x12 gray ft (aisle tile)	Gray	100.0	None	No Asbestos Detected	
MC-65 140802307-0025	12x12 tan ft	Various	96.6	None	3.4% Chrysotile	3.4
MC-65 140802307-0026	12x12 tan ft mastic	Black	100.0	None	<1% Chrysotile	<1
MC-66 140802307-0027	12x12 tan ft	Various				
Not Analyzed Positive stop						
MC-66 140802307-0028	12x12 tan ft mastic	Black	99.5	None	<1% Chrysotile	<1
MC-67 140802307-0029	mastic on vinyl cove molding	Brown	100.0	None	No Asbestos Detected	
MC-68 140802307-0030	mastic on vinyl cove molding	Brown	100.0	None	No Asbestos Detected	
MC-69 140802307-0031	floor leveler & carpet mastic	Various	100.0	None	No Asbestos Detected	
MC-70 140802307-0032	floor leveler & carpet mastic	Yellow/White	100.0	None	No Asbestos Detected	

Analyst(s)

Rhonda McGee (20)

Rhonda McGee

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:50 PM
EMSL Order: 140802307

EMSL Proj: Midtown
Analysis Date: 5/22/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-71 140802307-0033	brown battleship linoleum	Brown	99.2	None	<1% Chrysotile	<1
MC-72 140802307-0034	brown battleship linoleum	Brown	99.8	None	<1% Chrysotile	<1

Analyst(s)

Rhonda McGee (20)

Rhonda McGee

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

140807308

Liko Project # 08-21-104

JMD Services Project Number

MIDTOWN - McCreary's

Type of Survey and Address

Owner / Agent

May 08

Survey Date

24 HR 48 HR 3 DAY

6 Day

Number of Samples

Results Due By

Field Sample #	Material Description	Location	Amount	End	F/NF
MC-81	Cork/Tar Insulation	Barnment Bakery Area Sect. ①			
82	"	"			
83	9X9 TAN F.T. + MASTIC	Sub Basement Looking NW/Wing Per Sect ①			
84	"	"			
85	MASTIC ON VINYL C&E	Sect 4 2 nd Floor			
86	"	"			
87	Vapor Barrier under Terrazzo Floor	Sect 3 1 st Fl			
88	"	"			
89	Terrazzo Flooring	Sect 3 1 st Fl			
90	"	"			
91	Drywall Compound	Sect 3 3 rd Fl			
92	"	" 3 rd Fl			
93	"	" 3 rd Fl			
94	Drywall Compound	Sect 4 3			
95	"	" 4 2			
MC-96	"	" 4 1			

Comments / Special Instructions / Notes:

POS Stop per group.

(X) Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com



Sampled / Re-Inquired By

Date and Time

Received By

Barr DO 5-15-08 6:40 PM



1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax

140862308

Libo Project # 08-21-104

JMD Services Project Number

MICHAEL - McCune's
Type of Survey and Address

Owner / Agent

15 May 08
Survey Date

24 HR 48 HR 3 DAY
6 Day

Results Due By

Number of Samples

Field Sample #	Material Description	Location	Amount	End	F/N/F
MC- 97	Drywall Compound	Sect ②	3 rd		
98	"	" ③	2 nd		
99	"	" ②	1 st		
100	Drywall Compound	Sect ①	3 rd		
101	"	" ①	2 nd		
102	"	" ①	1 st		
103	Drywall Compound	Basement Sect ①			
104	"	" ②			
105	"	" ③			
106	Duct Insulation	Sect 1 Sub Basement			
107	"	" "			
108	"	Sect 1 Kt/Bkln			
109	12x12 Beige F.T.	Sect 2 2 nd			
110	"	" "			
111	Caulk/Sealant @ Walk-In Cooler	Sect 1 Basement			
MC- 112	"	" "			

NOT RECEIVED
DATE 5.16

Comments / Special Instructions / Notes:

Pos stop per Group

Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com


15 May

16 May 08 5:45:08 6:40 PM

Received By

Date and Time

Sampled / Relinquished By

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802308

EMSL Proj: Midtown
Analysis Date: 5/19/2008
Report Date: 5/22/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-81 140802308-0018	cork/tar insulation	Black/Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-82 140802308-0019	cork/tar insulation	Black/Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-83 140802308-0020	9x9 tan ft	Brown/Tan	92.7	None	7.3 Chrysotile 7.3 Total All Types
MC-83 140802308-0021	9x9 tan ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-84 140802308-0022	9x9 tan ft	Brown/Tan			
Not Analyzed positive stop					
MC-84 140802308-0023	9x9 tan ft mastic	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-85 140802308-0024	mastic on vinyl cove	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-86 140802308-0025	mastic on vinyl cove	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-87 140802308-0026	vapor barrier under terrazzo floor	Various	99.1	None	Inconclusive : <1 Chrysotile <1 Total All Types


Analyst(s)

Brian Walczak (10)
Tom Hanes (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method imitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802308

EMSL Proj: Midtown
Analysis Date: 5/19/2008
Report Date: 5/22/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-88 140802308-0027	vapor barrier under terrazzo floor	Black	98.1	None	1.9 Chrysotile 1.9 Total All Types
MC-109 140802308-0028	12x12 beige ft	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-110 140802308-0029	12x12 beige ft	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-111 140802308-0030	caulk/sealant @ walk-in coolers	Black	78.8	None	21.2 Chrysotile 21.2 Total All Types
MC-112 140802308-0031	caulk/sealant @ walk-in coolers	Black	100.0		
Not Analyzed positive stop					

Analyst(s)

Brian Walczak (10)
Tom Hanes (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802308

EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-89 140802308-0001	sect 3 1st fl	Beige Fibrous Homogeneous		99.75% Non-fibrous (other)	0.25% Chrysotile
MC-90 140802308-0002	sect 3 1st fl	Beige Fibrous Homogeneous		100.00% Non-fibrous (other)	<1% Chrysotile
MC-91 140802308-0003	sect 3 3rd fl	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-92 140802308-0004	sect 3 2nd fl	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-93 140802308-0005	sect 3 1st fl	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-94 140802308-0006	sect 4 3	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-95 140802308-0007	sect 4 2	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-96 140802308-0008	sect 4 1	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-97 140802308-0009	sect 2 3rd	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-98 140802308-0010	sect 2 2nd	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected

Analyst(s)

Andrew Maciejewski (19)
Tom Hanes (1)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

PLMPointCount-1

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802308

EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
MC-99 140802308-0011	sect 2 1st	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-100 140802308-0012	sect 1 3rd	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-101 140802308-0013	sect 1 2nd	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-102 140802308-0014	sect 1 1st	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-103 140802308-0015	basement sect 1	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-104 140802308-0016	basement sect 2	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-105 140802308-0017	basement sect 3	White Non-Fibrous Homogeneous		100.00% Non-fibrous (other)	None Detected
MC-106 140802308-0032	sect 1 sub basement	Gray Fibrous Homogeneous	3.00% Cellulose	70.00% Non-fibrous (other)	27.00% Chrysotile
MC-107 140802308-0033	sect 1 sub basement				Positive Stop
MC-108 140802308-0034	sect 1 kit/bakery				Positive Stop

Analyst(s)

Andrew Maciejewski (19)
Tom Hanes (1)

Rhonda McGee, Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

Analysis performed by EMSL Buffalo (NVLAP #200056-0), NY ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Robert Kreuzer**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104 / Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 05/15/08 6:40 PM
EMSL Order: 140802308
EMSL Proj: Midtown
Analysis Date: 5/21/2008
Report Date: 5/22/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-81 140802308-0018	cork/tar insulation	Black/Brown	100.0	None	No Asbestos Detected	
MC-82 140802308-0019	cork/tar insulation	Black/Brown	100.0	None	No Asbestos Detected	
MC-83 140802308-0021	9x9 tan ft mastic	Black	100.0	None	No Asbestos Detected	
MC-84 140802308-0023	9x9 tan ft mastic	Black	100.0	None	<1% Chrysotile	<1
MC-85 140802308-0024	mastic on vinyl cove	Black	100.0	None	No Asbestos Detected	
MC-86 140802308-0025	mastic on vinyl cove	Black	100.0	None	No Asbestos Detected	
MC-109 140802308-0028	12x12 beige ft	Gray	100.0	None	No Asbestos Detected	
MC-110 140802308-0029	12x12 beige ft	Gray	100.0	None	No Asbestos Detected	


Analyst(s)
Rhonda McGee (8)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

(716) 773-3400 phone (716) 773-3456 fax

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO:
Received: 06/20/08 4:00 PM
EMSL Order: 140803229

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **Midtown - MuCurdry's**

EMSL Proj: Midtown
Analysis Date: 6/24/2008
Report Date: 6/26/2008

**Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY
State ELAP 198.6 Method**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-160 140803229-0001	green linoleum	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-161 140803229-0002	green linoleum	Gray	100.0	None	Inconclusive: No Asbestos Detected
MC-162 140803229-0003	paper insulated metal CT	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-163 140803229-0004	paper insulated metal CT	Black	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Rachel Giese (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **Midtown - MuCurdry's**

Customer ID: LIRO50
Customer PO:
Received: 06/20/08 4:00 PM
EMSL Order: 140803229
EMSL Proj: Midtown
Analysis Date: 6/26/2008
Report Date: 6/26/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-160 140803229-0001	green linoleum	Gray	100.0	None	No Asbestos Detected	
MC-161 140803229-0002	green linoleum	Gray	100.0	None	No Asbestos Detected	
MC-162 140803229-0003	paper insulated metal CT	Black	100.0	None	No Asbestos Detected	
MC-163 140803229-0004	paper insulated metal CT	Black	100.0	None	No Asbestos Detected	

Analyst(s)

Tom Hanes (4)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

140802901

Libs Project 08-21-107

JMD Services Project Number

MSTOWN- MCCuey's

Type of Survey and Address

Survey Date

24 HR 48 HR 3 DAY

Per Lito

Number of Samples

Results Due By

Owner / Agent

Field Sample #	Material Description	Location	Amount	Cnd	F/NF
MC-160	Roof field	1	Bldg A		
161	"	2	"		
162	FLASHING	1	Bldg A		
163	"	2	"		
164	Roof field	1	Bldg B		
165	"	2	"		
166	FLASHING	1	Bldg B		
167	"	2	"		
168	Roof field	1	Bldg C		
169	"	2	"		
170	FLASHING	1	Bldg C		
171	"	2	"		
MC-172	COPIING TAR		Bldg C		

Comments / Special Instructions / Notes:

☒ Positive Stop per group

☒ Analyze PLM then TEM if negative AND NOB

email results to -- rbarr27@yahoo.com

Sampled / Relinquished By

BNK DO 0.10.08 2:55 PM

Received By

(B)

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104, Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 06/10/08 2:55 PM
EMSL Order: 140802901

EMSL Proj: Midtown
Analysis Date: 6/12/2008
Report Date: 6/16/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-160 140802901-0001	roof filed 1	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-161 140802901-0002	roof field 2	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-162 140802901-0003	flashing 1	Black/Red	81.4	None	18.6 Chrysotile 18.6 Total All Types
MC-163 140802901-0004	flashing 2	Black			
Not Analyzed Positive stop					
MC-164 140802901-0005	roof field 1	Black/Brown	100.0	None	Inconclusive : <1 Chrysotile <1 Total All Types
MC-165 140802901-0006	roof field 2	Black/Brown	99.9	None	Inconclusive : <1 Chrysotile <1 Total All Types
MC-166 140802901-0007	flashing 1	Black/Brown	100.0	None	Inconclusive: No Asbestos Detected
MC-167 140802901-0008	flashing 2	Black	98.5	None	1.5 Chrysotile 1.5 Total All Types
MC-168 140802901-0009	roof field 1	Various	100.0	None	Inconclusive: No Asbestos Detected

Analyst(s)

Rachel Giese (12)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104, Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 06/10/08 2:55 PM
EMSL Order: 140802901

EMSL Proj: Midtown
Analysis Date: 6/12/2008
Report Date: 6/16/2008

**Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY
State ELAP 198.6 Method**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES
MC-169 140802901-0010	roof field 2	Various	100.0	None	Inconclusive: No Asbestos Detected
MC-170 140802901-0011	flashing 1	Black	100.0	None	Inconclusive: No Asbestos Detected
MC-171 140802901-0012	flashing 2	Black/Brown	98.3	None	1.7 Chrysotile 1.7 Total All Types
MC-172 140802901-0013	copcing tar	Black	96.4	None	3.6 Chrysotile 3.6 Total All Types

Analyst(s)

Rachel Giese (12)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606



EMSL Analytical, Inc.

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **08-21-104, Midtown - McCurdy's**

Customer ID: LIRO50
Customer PO:
Received: 06/10/08 2:55 PM
EMSL Order: 140802901
EMSL Proj: Midtown
Analysis Date: 6/16/2008
Report Date: 6/16/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
MC-160 140802901-0001	roof filed 1	Black	100.0	None	No Asbestos Detected	
MC-161 140802901-0002	roof field 2	Black	100.0	None	No Asbestos Detected	
MC-164 140802901-0005	roof field 1	Black/Brown	100.0	None	<1% Chrysotile	<1
MC-165 140802901-0006	roof field 2	Black/Brown	100.0	None	<1% Chrysotile	<1
MC-168 140802901-0009	roof field 1	Various	100.0	None	No Asbestos Detected	
MC-169 140802901-0010	roof field 2	Various	100.0	None	No Asbestos Detected	

Analyst(s)

Rhonda McGee (6)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.
ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

140806587

8-1-08

24 HR 48 HR 3 DAY

Survey Date

Number of Samples

Owner / Agent

Results Due By

8/1/08

JMD Services Project Number
Midtown Mall

Type of Survey and Address

Field Sample #	Material Description	Location	Amount	Grid	Field
262	DRY WALL	RAINBOW			
263	DRY WALL COMPOUND				
264	"				
265	"				
266	PLASTER				
267	C/T				
268	12x12 F/T (WHITE)		54x30		
269	9x9 F/T (BEIGN)		12x6		
270	DRY WALL	FOOD COURT			
271	DRY WALL COMPOUND				
272	"				
273	"				
274	DRY WALL	NEWS STAND			
275	DRY WALL COMPOUND				
276	"				
277	"				

Comments / Special Instructions / Notes:

☐ Positive Stop per group

☒ Analyze PLM then TEM if negative AND NOB

email results to - rbarr27@yahoo.com

Sampled / Relinquished By

Date and Time

Received By

Date and Time

Grid

Field

Amount

Number of Samples

Survey Date

Owner / Agent

Results Due By

8/1/08

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

8/1/08 5pm

1470307421

JMD Services Project Number		Survey Date		24 HR 48 HR 3 DAY	
Midtown Mall		8-1-08		6-10 day 5 DAY	
Type of Survey and Address		Number of Samples		Results Due By	
Owner / Agent		Amount		End FINE	
Field Sample #	Material Description	Location			
278	DRY WALL	FOX NOUR			
279	DRY WALL compound	↓			
280	"				
281	"				
282	12x12 F/T (white)				
Comments / Special Instructions / Notes:					
<input type="checkbox"/> Positive Stop per group <input type="checkbox"/> Analyze PLM then TEM if negative AND NOB					
Sampled / Relinquished By		Date and Time		Received By	
VBC		8/15/08 5 pm		JDO 8/10/08 5 pm	
JMD SERVICES		1815 Love Road, Grand Island, NY 14072		email results to - rbarr27@yahoo.com Uncalibrated 08/10/08 10:03 AM	

(716) 773-3400 phone (716) 773-3456 fax

130826587



EMSL Analytical, Inc.

307 West :

Attn: **Liro Group**
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO: 08/06/08 10:03 AM
Received: 030826587
EMSL Order:
EMSL Proj:

Fax: (716) 882-9640
Project: **MIDTOWN MALL**
Phone: (716) 882-5476

Report Date: 8/7/2008

Asbestos Analysis of Bulk Material

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
262 030826587-0001 DRYWALL/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	Gray/Tan/W/hi	26.00% Cellulose	74%	None Detected	Not Analyzed
263 030826587-0002 DRYWALL COMPOUND/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	White		100%	None Detected	Not Analyzed
264 030826587-0003 DRYWALL COMPOUND/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	White		100%	None Detected	Not Analyzed
265 030826587-0004 DRYWALL COMPOUND/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	White		100%	None Detected	Not Analyzed
266 030826587-0005 PLASTER/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	White		100%	None Detected	Not Analyzed
266 ROUGH 030826587-0005A PLASTER/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	Gray/Tan		100%	None Detected	Not Analyzed
267 030826587-0006 C/T RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	Gray/White	30.00% Cellulose 50.00% Glass	20%	None Detected	Not Analyzed
268 030826587-0007 12X12 F/T WHITE/ RAINBOW	PLM NYS 198.1 Friable PLM NYS 198.6 NOB TEM NYS 198.4 NOB	8/6/2008	White		N/A	Inconclusive: None Detected	Not Analyzed
		8/7/2008	White		N/A	None Detected	Not Analyzed



EMSL Analytical, Inc.

307 West :

Attn: Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO:
Received: 08/06/08 10:03 AM
EMSL Order: 030826587
EMSL Proj:

Phone: (716) 882-5476
Fax: (716) 882-9640
Project: MIDTOWN MALL

Asbestos Analysis of Bulk Material

Report Date: 8/7/2008

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
268 M	PLM NYS 198.1 Friable						Not Analyzed
030826587-0007A	PLM NYS 198.6 NOB	8/6/2008	Black		N/A	Inconclusive: None Detected	
12X12 F/T WHITE/ RAINBOW	TEM NYS 198.4 NOB	8/7/2008	Black		N/A	None Detected	
269	PLM NYS 198.1 Friable						Not Analyzed
030826587-0008	PLM NYS 198.6 NOB	8/6/2008	Beige		N/A	1.3% Chrysotile 1.3% Total	
9X9 F/T BEIGE/ RAINBOW	TEM NYS 198.4 NOB	8/7/2008			N/A	Not Analyzed	Positive Stop
269 M	PLM NYS 198.1 Friable						Not Analyzed
030826587-0008A	PLM NYS 198.6 NOB	8/6/2008	Black		N/A	10.8% Chrysotile 10.8% Total	
9X9 F/T BEIGE/ RAINBOW	TEM NYS 198.4 NOB	8/7/2008			N/A	Not Analyzed	Positive Stop
270	PLM NYS 198.1 Friable	8/6/2008	Gray/Tan	12.00% Cellulose	88%	None Detected	NOTE: BEIGE MASTIC OMITTED
030826587-0009	PLM NYS 198.6 NOB				N/A		Not Analyzed
DRYWALL/ FOOD COURT	TEM NYS 198.4 NOB				N/A		Not Analyzed
271	PLM NYS 198.1 Friable	8/6/2008	White/Pink		100%	None Detected	
030826587-0010	PLM NYS 198.6 NOB				N/A		Not Analyzed
DRYWALL COMPOUND/ FOOD COURT	TEM NYS 198.4 NOB				N/A		Not Analyzed
272	PLM NYS 198.1 Friable	8/6/2008	White/Pink		100%	None Detected	
030826587-0011	PLM NYS 198.6 NOB				N/A		Not Analyzed
DRYWALL COMPOUND/ FOOD COURT	TEM NYS 198.4 NOB				N/A		Not Analyzed
273	PLM NYS 198.1 Friable	8/6/2008	White/Pink		100%	None Detected	
030826587-0012	PLM NYS 198.6 NOB				N/A		Not Analyzed
DRYWALL COMPOUND/ FOOD COURT	TEM NYS 198.4 NOB				N/A		Not Analyzed



EMSL Analytical, Inc.

307 West :

Attn: Liro Group
690 Delaware Avenue
Buffalo, NY 14209


Customer ID: LIRO50
Customer PO: 08/06/08 10:03 AM
Received: 030826587
EMSL Order:
EMSL Proj:

Phone: (716) 882-5476
Fax: (716) 882-9640
Project: MIDTOWN MALL

Asbestos Analysis of Bulk Material

Report Date: 8/7/2008

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
274 030826587-0013	PLM NYS 198.1 Friable	8/6/2008	Gray/Tan	10.00% Cellulose <1% Glass	90%	None Detected	
DRYWALL / NEWSTAND	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed
	PLM NYS 198.1 Friable	8/6/2008	White/Gray		100%	None Detected	
	PLM NYS 198.6 NOB			N/A			Not Analyzed
275 030826587-0014	TEM NYS 198.4 NOB			N/A			Not Analyzed
DRYWALL COMPOUND/ NEWSTAND	PLM NYS 198.1 Friable	8/6/2008	White/Gray		100%	None Detected	
	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed
	PLM NYS 198.1 Friable	8/6/2008	White/Gray		100%	None Detected	
276 030826587-0015	PLM NYS 198.6 NOB			N/A			Not Analyzed
DRYWALL COMPOUND/ NEWSTAND	TEM NYS 198.4 NOB			N/A			Not Analyzed
	PLM NYS 198.1 Friable	8/6/2008	White/Gray		100%	None Detected	
	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed
277 030826587-0016	PLM NYS 198.1 Friable	8/6/2008	White/Gray		100%	None Detected	
DRYWALL COMPOUND/ NEWSTAND	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed
	PLM NYS 198.1 Friable	8/6/2008	White/Gray		100%	None Detected	
	PLM NYS 198.6 NOB			N/A			Not Analyzed
278 030826587-0017	TEM NYS 198.4 NOB			N/A			Not Analyzed
DRYWALL/ FOXNOUR	PLM NYS 198.1 Friable	8/6/2008	Gray/Tan	13.00% Cellulose <1% Glass	87%	None Detected	
	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed
	PLM NYS 198.1 Friable	8/6/2008	White/Cream		100%	None Detected	
279 030826587-0018	PLM NYS 198.6 NOB			N/A			Not Analyzed
DRYWALL COMPOUND/ FOXNOUR	TEM NYS 198.4 NOB			N/A			Not Analyzed
	PLM NYS 198.1 Friable	8/6/2008	White/Cream		100%	None Detected	
	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed
280 030826587-0019	PLM NYS 198.1 Friable	8/6/2008	White/Cream		100%	None Detected	
DRYWALL COMPOUND/ FOXNOUR	PLM NYS 198.6 NOB			N/A			Not Analyzed
	TEM NYS 198.4 NOB			N/A			Not Analyzed



EMSL Analytical, Inc.

307 West :

Attn: Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO: 08/06/08 10:03 AM
Received: 030826587
EMSL Order:
EMSL Proj:

Phone: (716) 882-5476
Fax: (716) 882-9640
Project: MIDTOWN MALL

Asbestos Analysis of Bulk Material

Report Date: 8/7/2008

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
281 030826587-0020 DRYWALL COMPOUND/ FOXNOUR	PLM NYS 198.1 Friable	8/6/2008	White/Cream		100%	None Detected	
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
282 030826587-0021	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	8/6/2008	Beige		N/A	Inconclusive : <1% Chrysotile <1% Total	
	TEM NYS 198.4 NOB	8/7/2008	Beige		N/A	None Detected	
12X12 F/T WHITE							

NOB = Non Friable Organically Bound
N/A = Not Applicable

Analyst(s)

Robert Georgens
Steve Juscuk

James Hall, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The results in this report meet all requirements of the NELAC Standards unless otherwise noted. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB's. Quantitative TEM is currently the only method that can be used to determine if a NOB material can be considered or treated as non-asbestos containing.

ACCREDITATIONS: NVLAP #101048-9 and NY STATE ELAP #11506

030828362

Midtown Skyways

JMD Services Project Number

8/14/05

Survey Date

24 HR 48 HR 3 DAY

5 DAY

Results Due By

Owner / Agent

Number of Samples

Type of Survey and Address

SW

SW

01	SPRAY ON	SEN / CHASE
02	WINDOW CAULK	SEN / CHASE
03	ROOFING	SEN / CHASE
04	FLASHING	SEN / CHASE
05	ROOFING	SEN / CHASE
06	FLASHING	SEN / CHASE
07	PLASTER	Sibley
08	"	Sibley
09	"	Sibley
10	Stucco	Sibley
11	"	Sibley
12	"	Sibley
13	CAULK (Ext Pannel)	Sibley
14	ROOFING	Sibley
15	ROOFING	Sibley

Clinton Ave

Main Street

Overlapper

email results to - rhart27@yahoo.com

Nick Solich


08-15-08P12:28 RCVD LUCAS

relinquished JMD 08-15-08 5:30pm

JMD SERVICES

1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax



EMSL Analytical, Inc.

307 West

Attn: **Liro Group**
690 Delaware Avenue
Buffalo, NY 14209

LIRO50

Customer ID:
Customer PO:
Received:
EMSL Order:
EMSL Proj:

08/18/08 10:35 AI
030828362
Midtown

Fax: (716) 882-9640
Phone: (716) 882-5476
Project: **MIDTOWN SKYWALKS**

Report Date: 8/23/2008

Asbestos Analysis of Bulk Material

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
01 030828362-0001 SPRAY ON JEN/CHASE	PLM NYS 198.1 Friable	8/22/2008	Tan	5.00% Cellulose 80.00% Glass	15%	None Detected	
	PLM NYS 198.6 NOB				N/A		Not Analyzed
02 030828362-0002 WINDOW CAULK JEN/CHASE	TEM NYS 198.4 NOB				N/A		Not Analyzed
	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	8/19/2008	Brown		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	8/22/2008	Brown		N/A	None Detected	
03 030828362-0003 ROOFING JEN/CHASE	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	8/19/2008	Gray		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	8/22/2008	Gray		N/A	None Detected	
	PLM NYS 198.1 Friable						Not Analyzed
04 030828362-0004 FLASHING JEN/ CHASE	PLM NYS 198.6 NOB	8/19/2008	Black		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	8/22/2008	Black		N/A	1.4% Chrysotile 1.4% Total	
	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	8/19/2008	Tan/Black	<1% Glass	N/A	Inconclusive: None Detected	
05 030828362-0005 ROOFING JEN/ CHASE	TEM NYS 198.4 NOB	8/22/2008	Tan/Black		N/A	None Detected	
	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	8/19/2008	Black		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	8/22/2008	Black		N/A	<1% Chrysotile <1% Total	
06 030828362-0006 FLASHING JEN/ CHASE	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	8/19/2008	Tan/White		100%	None Detected	
	TEM NYS 198.4 NOB	8/22/2008			N/A		Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
07 030828362-0007 PLASTER SIBLEY	PLM NYS 198.1 Friable	8/22/2008			N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed



EMSL Analytical, Inc.

307 West

Attn: Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO: 08/18/08 10:35 AM
Received: 030828362
EMSL Order: Midtown
EMSL Proj:

Phone: (716) 882-5476
Fax: (716) 882-9640
Project: MIDDOWN SKYWALKS

Report Date: 8/23/2008

Asbestos Analysis of Bulk Material

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
08 030828362-0008 PLASTER SIBLEY	PLM NYS 198.1 Friable	8/22/2008	Gray/White		100%	None Detected	Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
09 030828362-0009 PLASTER SIBLEY	PLM NYS 198.1 Friable	8/22/2008	Gray/White		100%	None Detected	Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
10 030828362-0010 STUCCO SIBLEY	PLM NYS 198.1 Friable	8/22/2008	Gray/White		100%	None Detected	Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
11 030828362-0011 STUCCO SIBLEY	PLM NYS 198.1 Friable	8/22/2008	Gray/White		100%	None Detected	Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
12 030828362-0012 STUCCO SIBLEY	PLM NYS 198.1 Friable	8/22/2008	Gray/White		100%	None Detected	Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
13 030828362-0013 CAULK (EXT PANEL) SIBLEY	PLM NYS 198.1 Friable	8/22/2008	Gray/White		100%	None Detected	Not Analyzed
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
14 030828362-0014 ROOFING SIBLEY	PLM NYS 198.1 Friable	8/19/2008	Gray/Black		N/A	Inconclusive: None Detected	Not Analyzed
	PLM NYS 198.6 NOB	8/22/2008	Gray/Black		N/A	None Detected	Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
15 030828362-0015 ROOFING SIBLEY	PLM NYS 198.1 Friable	8/19/2008	Brown/Tan	<1% Glass	N/A	Inconclusive: None Detected	Not Analyzed
	PLM NYS 198.6 NOB	8/22/2008	Brown/Tan		N/A	None Detected	Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed



EMSL Analytical, Inc.

307 West

Attn: Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Customer ID: LIRO50
Customer PO:
Received: 08/18/08 10:35 AM
EMSL Order: 030828362
EMSL Proj: Midtown

Fax: (716) 882-9640
Project: MIDTOWN SKYWALKS
Phone: (716) 882-5476

Asbestos Analysis of Bulk Material

Report Date: 8/23/2008

Sample Description	Test	Analyzed Date	Color	Fibrous	Non Asbestos	Non-Fibrous	Asbestos	Comments
--------------------	------	---------------	-------	---------	--------------	-------------	----------	----------

NOB = Non Friable Organically Bound
N/A = Not Applicable

Analyst(s)



Alexander Balter
Ping Chen

James Hall, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The results in this report meet all requirements of the NELAP Standards unless otherwise noted. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB's. Quantitative TEM is currently the only method that can be used to determine if a NOB material can be considered or treated as non-asbestos containing.

ACCREDITATIONS: NVLAP #101048-9 and NY STATE ELAP #11506


140804293

JMD Services Project Number MIDTOWN EXTERIOR		Survey Date 8/1/08		24 HR 48 HR 3 DAY 6-10 day	
Type of Survey and Address		Number of Samples 10		Results Date By 8/1/08	
Owner / Agent		Amount		End Date	
Field Sample #	Material Description	Location	Amount	End Date	
ME01	CAULK	Euclid St Entrance			
ME02	"	"			
ME03	CAULK	MINUTE MAN			
ME04	"	"			
ME05	CAULK	IN BETWEEN BLUE MARBLE			
ME06	"	"			
ME07	CAULK	CLINTON ST DOOR			
ME08	"	"			
ME09	CAULK	MARBLE MEETS SIDEWALK - McCurdy's Bldg			
ME10	"	" - B. Forman Bldg			
Comments / Special Instructions / Notes:					
<input type="checkbox"/> Positive Stop per group <input checked="" type="checkbox"/> Analyze PLM then TEM if negative AND NOB					
				email results to - rbarr27@yahoo.com 8/1/08 5 pm	
Sampled / Requisitioned By		Date and Time		Received By	

JMD
SERVICES

1815 Love Road, Grand Island, NY 14072

(716) 773-3400 phone (716) 773-3456 fax

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: (716) 651-0394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **Midtown Exterior**

Customer ID: LIRO50
Customer PO:
Received: 08/01/08 5:00 PM
EMSL Order: 140804293
EMSL Proj: Midtown
Analysis Date: 8/6/2008
Report Date: 8/13/2008

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.6 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	
01 140804293-0001	caulk	White	99.7	None	Inconclusive : <1 Chrysotile <1 Total All Types	Euclid
02 140804293-0002	caulk	White	99.9	None	Inconclusive : <1 Chrysotile <1 Total All Types	Euclid
03 140804293-0003	caulk	Black	99.4	None	Inconclusive : <1 Chrysotile <1 Total All Types	Euclid
04 140804293-0004	caulk	Black	99.5	None	Inconclusive : <1 Chrysotile <1 Total All Types	Euclid
05 140804293-0005	caulk	Black	100.0	None	Inconclusive: No Asbestos Detected	McCurdy
06 140804293-0006	caulk	Black	100.0	None	Inconclusive: No Asbestos Detected	McCurdy
07 140804293-0007	caulk	Gray	100.0	None	Inconclusive: No Asbestos Detected	Mall
08 140804293-0008	caulk	Gray	100.0	None	Inconclusive: No Asbestos Detected	Mall
09 140804293-0009	caulk	Black/Gray	100.0	None	Inconclusive: No Asbestos Detected	McCurdy
10 140804293-0010	caulk	Black/Gray	100.0	None	Inconclusive: No Asbestos Detected	B. Forman

Analyst(s)

Andrew Maciejewski (5)
Rachel Giese (5)

Rhonda McGee, Laboratory Manager
or other approved signatory

*Polarized Light Microscopy (PLM) is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative Transmission Electron Microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The test results contained within this report meet the requirements of NELAC unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method imitations. Unless otherwise noted, the results in this report have not been blank corrected. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone: (716) 651-0030 Fax: 7166510394 Email: buffalolab@emsl.com

Attn: **Jason Colvin**
Liro Group
690 Delaware Avenue
Buffalo, NY 14209

Fax: (716) 882-9640 Phone: (716) 882-5476
Project: **Midtown Exterior**

Customer ID: LIRO50
Customer PO:
Received: 08/01/08 5:00 PM
EMSL Order: 140804293

EMSL Proj: Midtown
Analysis Date: 8/13/2008
Report Date: 8/13/2008

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
01 140804293-0001	caulk	White	99.8	None	<1% Chrysotile	<1 <i>Euclid</i>
02 140804293-0002	caulk	White	99.8	None	<1% Chrysotile	<1 <i>Euclid</i>
03 140804293-0003	caulk	Black	98.1	None	1.9% Chrysotile	1.9 <i>Euclid</i>
04 140804293-0004	caulk	Black	98.2	None	1.8% Chrysotile	1.8 <i>Euclid</i>
05 140804293-0005	caulk	Black	100.0	None	No Asbestos Detected	<i>McCurdy</i>
06 140804293-0006	caulk	Black	100.0	None	No Asbestos Detected	<i>McCurdy</i>
07 140804293-0007	caulk	Gray	100.0	None	No Asbestos Detected	<i>mall</i>
08 140804293-0008	caulk	Gray	100.0	None	No Asbestos Detected	<i>mall</i>
09 140804293-0009	caulk	Black/Gray	100.0	None	No Asbestos Detected	<i>McCurdy</i>
10 140804293-0010	caulk	Black/Gray	100.0	None	No Asbestos Detected	<i>B. Forman</i>

Analyst(s)

Rhonda McGee (10)

Rhonda McGee, Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted.

ACCREDITATIONS: NVLAP #200056-0 and NY STATE ELAP #11606

0208 39120

Liro Engineers, Inc.
ENVIRONMENTAL & ENGINEERING SERVICES

690 Delaware Avenue
 Buffalo, New York 14209
 Tel. 716-882-5476 / Fax 716-882-9640

Bulk Sampling Chain of Custody Form

Liro Job:
Job Name: Midtown Plaza
Job Location: Midtown Plaza, Rochester NY
Building /Site: McCurdy's

FAX Results to: 716-882-9640
attention: Jason Colvin
email results to: colvinj@liro.com
Turn-Around-Time: 3 day

ACM Code	Sample Number	SAMPLE LOCATION	DESCRIPTION OF MATERIAL	MATERIAL QUANTITY (sf, lf, cy)	NOTES
MC1	M-G01A	sub-basement boiler room	boiler door rope gasket		
MC1	M-G01B	sub-basement boiler room	boiler door rope gasket		
MC2	MC-EC01A *	exterior	louver caulk		
MC2	MC-EC01B *	exterior	louver caulk		
MC3	MC-EC02A *	exterior 5th floor	window caulk		
MC3	MC-EC02B *	exterior 5th floor	window caulk		

RECEIVED
 EMS, MANHATTAN
 08 NOV -1 AM 9:20

Comments: First positive stop for each "ACM Code" Group.

Analyze NYS friables via PLM only. Analyze NYS NOB via PLM to TEM.

Relinquished By (Signature) <i>Jason Colvin</i>	Date / Time 11/3/08	Received By (Signature) <i>ngoursal</i>	Date / Time 11/4/08
--	------------------------	--	------------------------



EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018
(212) 290-0051

Attn: **Jason Colvin**
Liro Engineers, Inc.
3 Aerial Way
Syosset, NY 11791

Fax: (212) 563-1841 Phone: (516) 938-5476
Project: **McCURDY'S/MIDTOWN PLAZA/ ROCHESTER, NY**

Customer ID: LIRO50A
Customer PO:
Received: 11/04/08 9:20 AM
EMSL Order: 030839120

EMSL Proj:

Report Date: 11/7/2008

Asbestos Analysis of Bulk Material

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		
M-G01A 030839120-0001 SUB BASEMENT BOILER RM/ BOILER DOOR ROPE GASKET	PLM NYS 198.1 Friable	11/5/2008	Gray/Tan	98.00% Glass	2%	None Detected	
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
M-G01B 030839120-0002 SUB BASEMENT BOILER RM/ BOILER DOOR ROPE GASKET	PLM NYS 198.1 Friable	11/5/2008	Gray/Tan	96.00% Glass	4%	None Detected	
	PLM NYS 198.6 NOB				N/A		Not Analyzed
	TEM NYS 198.4 NOB				N/A		Not Analyzed
MC-EC01A 030839120-0003 EXTERIOR/ LOUVER CAULK	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	11/5/2008	Gray		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	11/7/2008	Gray		N/A	None Detected	
MC-EC01B 030839120-0004 EXTERIOR/ LOUVER CAULK	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	11/5/2008	White		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	11/7/2008	White		N/A	None Detected	
MC-EC02A 030839120-0005 EXTERIOR 5TH FLOOR/ WINDOW CAULK	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	11/5/2008	Gray		N/A	Inconclusive : <1% Chrysotile <1% Total	
	TEM NYS 198.4 NOB	11/7/2008	Gray		N/A	<1% Chrysotile <1% Total	
MC-EC02B 030839120-0006 EXTERIOR 5TH FLOOR/ WINDOW CAULK	PLM NYS 198.1 Friable						Not Analyzed
	PLM NYS 198.6 NOB	11/5/2008	Gray		N/A	Inconclusive: None Detected	
	TEM NYS 198.4 NOB	11/7/2008	Gray		N/A	None Detected	



EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018
(212) 290-0051

Attn: **Jason Colvin**
Liro Engineers, Inc.
3 Aerial Way
Syosset, NY 11791

Fax: (212) 563-1841 Phone: (516) 938-5476
Project: **McCURDY'S/MIDTOWN PLAZA/ ROCHESTER, NY**

Customer ID: LIRO50A
Customer PO:
Received: 11/04/08 9:20 AM
EMSL Order: 030839120
EMSL Proj:
Report Date: 11/7/2008

Asbestos Analysis of Bulk Material

Sample Description	Test	Analyzed Date	Color	Non Asbestos		Asbestos	Comments
				Fibrous	Non-Fibrous		

NOB = Non Friable Organically Bound
N/A = Not Applicable

Analyst(s)

George Williams

Steve Juszczuk

James Hall, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The results in this report meet all requirements of the NELAC Standards unless otherwise noted. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB's. Quantitative TEM is currently the only method that can be used to determine if a NOB material can be considered or treated as non-asbestos containing.

ACCREDITATIONS: NVLAP #101048-9 and NY STATE ELAP #11506

108121324

Bulk Sampling Chain of Custody Form

McCurdy's Building

Turn-Around-Time:	24 hour
<p>  </p>	

Comments: First positive stop.

Analyze PLM only.

Relinquished By (Signature)

Date / Time /

Received By (Signature)

Date / Time

RECEIVED

DEC 12 2008

rk

**AMERISCI****AmeriSci Richmond**13635 GENITO ROAD
MIDLOTHIAN, VIRGINIA 23112
TEL: (804) 763-1200 • FAX: (804) 763-1800**PLM Bulk Asbestos Report**Liro-Kreuzer, Inc.
Attn: Jason Colvin
690 Delaware Avenue

Buffalo, NY 14209**Date Received** 12/12/08 **AmeriSci Job #** 108121324
Date Examined 12/12/08 **P.O. #**
ELAP # 10984 **Page** 1 **of** 1
RE: Midtown Plaza; Midtown Plaza, Rochester, NY; McCurdy's Building

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
MC-173 1	108121324-01 Location: McCurdy's Roof; Spray-On Fireproofing On Elevator Shaft I-Beam	Yes	18.2 % (by NYS ELAP 198.1) by Gordon T. Saleeby on 12/12/08
Analyst Description: Off White, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 18.2 % Other Material: Fibrous glass 75 %, Non-fibrous 6.8 %			
MC-174 1	108121324-02 Location: McCurdy's Roof; Spray-On Fireproofing On Elevator Shaft I-Beam		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			

Reporting Notes:

Analyzed by: Gordon T. Saleeby *Gordon T. Saleeby* Date *Dec 12, 2008*
*NAD = no asbestos detected, Detection Limit <1%, Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Code 101904-0) and ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples)(NYS DOH ELAP Lab # 10984); CA ELAP Lab # 2508; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____



Report of Asbestos Survey Services

APPENDIX B:

LABORATORY ACCREDITATIONS AND PERSONNEL CERTIFICATIONS

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER
RICHARD F. DAINES, M.D.



Expires 12:01 AM April 01, 2009
Issued April 01, 2008
Revised June 12, 2008

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. RHONDA R. MCGEE
EMSL ANALYTICAL INC
400 ROWLEY ROAD
DEPEW, NY 14043

NY Lab Id No: 11606
EPA Lab Code: NY01278

*is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES AIR AND EMISSIONS
All approved subcategories and/or analytes are listed below:*

Miscellaneous Air

Asbestos

40 CFR 763 APX A No. III

NIOSH 7402

YAMATE, AGARWAL GIBB


Filters

NIOSH 7400 A RULES

Serial No.: 37178

Property of the New York State Department of Health. Valid only at the address shown. Must be conspicuously posted. Valid certificates have a raised seal. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (516) 480-8070 to verify laboratory's accreditation status.

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 200056-0

EMSL Analytical, Inc.
Depew, NY

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for:*

BULK ASBESTOS FIBER ANALYSIS

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-ILAC-IAF Communiqué dated 18 June 2005).*

2008-07-01 through 2009-06-30

Effective dates



For the National Institute of Standards and Technology

Debbie L. Bowers



**National Voluntary
Laboratory Accreditation Program**



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

EMSL Analytical, Inc.
490 Rowley Road
Depew, NY 14043
Mr. Kenneth J. Najuch
Phone: 716-651-0030 Fax: 716-651-0394
E-Mail: knajuch@emsl.com
URL: <http://www.emsl.com/>

BULK ASBESTOS FIBER ANALYSIS (PLM)

NVLAP LAB CODE 200056-0


NVLAP Code Designation / Description

18/A01	EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples
--------	--

2008-07-01 through 2009-06-30

Effective dates

Sally S. Bruce
For the National Institute of Standards and Technology



NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER
RICHARD F. DAINES, M.D.



Expires 12:01 AM April 01, 2009
Issued April 01, 2008

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

DR. THOMAS MCKEE
AMERISCI RICHMOND
13635 GENITO RD
MIDLOTHIAN, VA 23112

NY Lab Id No: 10984
EPA Lab Code: VA00911

*is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE
All approved subcategories and/or analytes are listed below:*


Miscellaneous

Asbestos in Friable Material	EPA 600/M4/82/020 Item 198.1 of Manual
Asbestos in Non-Friable Material-PLM	Item 198.6 of Manual (NOB by PLM)
Asbestos in Non-Friable Material-TEM	ITEM 198.4 OF MANUAL

Serial No.: 36014

Property of the New York State Department of Health. Valid only at the address shown. Must be conspicuously posted. Valid certificates have a raised seal. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify laboratory's accreditation status.

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 101904-0

AmeriSci Richmond
Midlothian, VA


*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for.*

BULK ASBESTOS FIBER ANALYSIS

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-ILAC-IAF Communique dated 18 June 2005).*

2008-07-01 through 2009-06-30

Effective dates



Sally A. Bruce
For the National Institute of Standards and Technology



**National Voluntary
Laboratory Accreditation Program**



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

AmeriSci Richmond
dba AmeriSci Richmond
13635 Genito Road
Midlothian, VA 23112
Mr. Thomas B. Keith
Phone: 804-763-1200 Fax: 804-763-1800
E-Mail: bkeith@amerisci.com
URL: <http://www.amerisci.com>

BULK ASBESTOS FIBER ANALYSIS (PLM)

NVLAP LAB CODE 101904-0

NVLAP Code Designation / Description



18/A01 EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

2008-07-01 through 2009-06-30

Effective dates

Sally S. Bruce
For the National Institute of Standards and Technology

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE




CERT# 93-19183
DMV# 500957382

MUST BE CARRIED ON ASBESTOS PROJECTS

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



JASON J. COLVIN
CLASS(EXPIRES)
C ATEC(04/09) D INSP(04/09)
H PM (04/09)



CERT# 02-02820
DMV# 801923361

MUST BE CARRIED ON ASBESTOS PROJECTS





EYES BRO
HAIR BRO
HGT 6' 00"

IF FOUND RETURN TO:
NYSOL - L&C UNIT
ROOM 290A BUILDING 12
STATE OFFICE CAMPUS
ALBANY NY 12240



Report of Asbestos Survey Services

APPENDIX C: BULK SAMPLE LOCATION DRAWINGS



LEGEND:

- MC-06
- MC-06

SAMPLE LOCATION (POSITIVE)
SAMPLE LOCATION (NEGATIVE)

Scale: 0 15 30 Ft.

WARNING

IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.

NO.	DATE	DESCRIPTION
REVISIONS		





Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:	CLIENT:	
DESIGNED BY:	Empire State Development 400 Andrews Street, Suite 100 Rochester, New York 14604-1409	
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:	McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK
DRAWING TITLE:	SUB-BASEMENT BULK SAMPLE LOCATION PLAN

LIRO JOB NO.:	08-21-104
SHEET	OF
1	10
FIGURE NO.	BSL-1

4082104-1-Midtown Plaza CAD SURVEY VBSL.MCCURDY SURVEY.DWG, 12/2/2008, 14:50:05 PM, AMK



LEGEND:

- MC-06 SAMPLE LOCATION (POSITIVE)
MC-06 SAMPLE LOCATION (NEGATIVE)

Scale: 0 15 30 Ft.

WARNING

IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.

NO.	DATE	DESCRIPTION
REVISIONS		



Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:

DESIGNED BY:

CHECKED BY:

DRAWN BY:

CLIENT:

Empire State Development

400 Andrews Street, Suite 100
Rochester, New York 14604-1409

DATE:

SEPTEMBER 2008

SCALE:

AS SHOWN

JOB TITLE AND LOCATION:

McCURDY'S BUILDING
MIDTOWN PLAZA
ROCHESTER, NEW YORK

DRAWING TITLE:

**BASEMENT
BULK SAMPLE LOCATION PLAN**

LIRO JOB NO.:

08-21-104


SHEET OF

2 10

FIGURE NO.

BSL-2





LEGEND:

- MC-06 SAMPLE LOCATION (POSITIVE)
MC-06 SAMPLE LOCATION (NEGATIVE)

Scale: 0 15 30
Ft.

WARNING

IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.



NO.	DATE	DESCRIPTION
REVISIONS		



Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:	CLIENT:	
DESIGNED BY:	Empire State Development 400 Andrews Street, Suite 100 Rochester, New York 14604-1409	
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:	McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK	LIRO JOB NO.: 08-21-104
DRAWING TITLE:	2ND FLOOR BULK SAMPLE LOCATION PLAN	SHEET 4 OF 10
		FIGURE NO. BSL-4



LEGEND:

- MC-06 SAMPLE LOCATION (POSITIVE)
- MC-06 SAMPLE LOCATION (NEGATIVE)

Scale: 0 15 30 Ft.

WARNING
IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE
EDU

REVISIONS



Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:

DESIGNED BY:

CHECKED BY:

DRAWN BY:

CLIENT:

Empire State Development

400 Andrews Street, Suite 100
Rochester, New York 14604-1409

DATE: SEPTEMBER 2008

SCALE: AS SHOWN

JOB TITLE AND LOCATION:

McCURDY'S BUILDING
MIDTOWN PLAZA
ROCHESTER, NEW YORK

DRAWING TITLE:



3RD FLOOR
BULK SAMPLE LOCATION PLAN

LIRO JOB NO.:
08-21-104

SHEET OF
5 10


FIGURE NO.

BSL-5



LEGEND:

-  **MC-06** SAMPLE LOCATION (POSITIVE)
-  **MC-06** SAMPLE LOCATION (NEGATIVE)

Scale:  0 15 30 Ft.

WARNING

IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.


NO.	DATE	DESCRIPTION
REVISIONS		



Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York


PROJ. ENG.:	CLIENT:	
DESIGNED BY:	Empire State Development 400 Andrews Street, Suite 100 Rochester, New York 14604-1409	
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:	McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK	LIRO JOB NO.: 08-21-104
		SHEET 6 OF 10
DRAWING TITLE:	4TH FLOOR BULK SAMPLE LOCATION PLAN	FIGURE NO. BSL-6



LEGEND:

- MC-06 SAMPLE LOCATION (POSITIVE)
- MC-06 SAMPLE LOCATION (NEGATIVE)



WARNING
IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.



NO.	DATE	DESCRIPTION
REVISIONS		



Lito Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:	CLIENT:	
DESIGNED BY:	Empire State Development 400 Andrews Street, Suite 100 Rochester, New York 14604-1409	
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:	McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK
DRAWING TITLE:	5TH FLOOR BULK SAMPLE LOCATION PLAN



WARNING

IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.



NO.	DATE	DESCRIPTION
REVISIONS		




Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:	CLIENT:	
DESIGNED BY:	Empire State Development 400 Andrews Street, Suite 100 Rochester, New York 14604-1409	
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:	McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK		LIRO JOB NO.:
	DRAWING TITLE:		08-21-104
			SHEET
8 10			
FIGURE NO.			
BSL-8			



LEGEND:



SAMPLE LOCATION (POSITIVE)
SAMPLE LOCATION (NEGATIVE)



WARNING
IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.

NO.	DATE	DESCRIPTION
REVISIONS		



Lito Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:	Empire State Development 400 Andrews Street, Suite 100 Rochester, New York 14604-1409	
DESIGNED BY:		
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:	McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK	LIRO JOB NO.: 08-21-104
DRAWING TITLE:	ROOF BULK SAMPLE LOCATION PLAN	SHEET 9 OF 10
		FIGURE NO. BSL-9



MONROE COMMUNITY COLLEGE/SIBLEY OFFICE BUILDINGS
SHOPS AT SIBLEYS

LIBERTY
POLE

MAIN STREET EAST

- SW-14
- SW-07
- SW-12
- SW-08
- SW-11
- SW-15
- SW-13
- SW-09
- SW-10

ROCHESTER
COMMUNITY
SAVINGS
BANK

McCURDY'S
OFFICE BUILDING
& RETAIL SHOPS

FLEET
BANK

LEGEND:

- MC-06 SAMPLE LOCATION (POSITIVE)
- MC-06 SAMPLE LOCATION (NEGATIVE)

Scale: 0 15 30 Ft.

WARNING
IT IS A VIOLATION OF SECTION 7209, SUBDIVISION 2, OF THE NEW YORK STATE
EDUCATION LAW FOR ANY PERSON, OTHER THAN THOSE WHOSE SEAL APPEARS
ON THIS DRAWING, TO ALTER IN ANY WAY AN ITEM ON THIS DRAWING. IF AN
ITEM IS ALTERED, THE ALTERING ENGINEER SHALL AFFIX TO THE ITEM HIS SEAL
AND THE NOTATION "ALTERED BY" FOLLOWED BY HIS SIGNATURE AND THE DATE
OF SUCH ALTERATION, AND A SPECIFIC DESCRIPTION OF THE ALTERATION.

NO.	DATE	DESCRIPTION
REVISIONS		



Liro Engineers, Inc.
690 Delaware Ave.
Buffalo, New York

PROJ. ENG.:	<div>CLIENT:</div> <div>Empire State Development</div> <div>400 Andrews Street, Suite 100 Rochester, New York 14604-1409</div>	
DESIGNED BY:		
CHECKED BY:		
DRAWN BY:		
DATE:	SEPTEMBER 2008	SCALE: AS SHOWN

JOB TITLE AND LOCATION:		LIRO JOB NO.: 08-21-104
McCURDY'S BUILDING MIDTOWN PLAZA ROCHESTER, NEW YORK		SHEET 10 OF 10
DRAWING TITLE:		FIGURE NO.
MAIN STREET SKYWALK BULK SAMPLE LOCATION PLAN		BSL-10



Report of Asbestos Survey Services

APPENDIX D: PHOTOGRAPHIC LOG



Report of Asbestos Survey Services



IMG 1618



IMG 1624



IMG 1581



IMG 1620



IMG 1611



IMG 1595



Report of Asbestos Survey Services



IMG 1655 – duct insulation blocks



ACM Transite ceiling panels in basement



ACM Transite boards



Report of Asbestos Survey Services

APPENDIX E:

SEAR-BROWN GROUP FRIABLE ASBESTOS CONTAINING MATERIALS SURVEY

FRIABLE ASBESTOS CONTAINING BUILDING MATERIALS SURVEY

**McCURDY'S BUILDING
EAST MAIN STREET/MIDTOWN PLAZA
ROCHESTER, NEW YORK**

JUNE 1992

Prepared for:

**CHASE LINCOLN FIRST BANK, N.A.
ONE LINCOLN FIRST SQUARE
ROCHESTER, NEW YORK 14604**

and

McCURDY & COMPANY, INC.

and

MARINE MIDLAND BANK, N.A.

and

CENTRAL TRUST COMPANY

Prepared by:

**THE SEAR-BROWN GROUP, INC.
85 METRO PARK
ROCHESTER, NEW YORK 14623**

**COPYRIGHT® 1992
The Sear-Brown Group**

Table of Contents

Section

1. Introduction and Approach
2. Survey Methods
3. Results and Discussion
4. Removal Cost Estimate

Tables

Table 1 - Friable Asbestos Containing Building Materials Survey Results

Table 2 - Friable ACBM Removal Cost Estimate

Figures

Figure 1 - USEPA Asbestos Hazard Assessment Tree

Appendices

Appendix A - Asbestos Bulk Sampling Data Sheets

Appendix B - Laboratory Results

Appendix C - Floor Plans

Appendix D - USEPA Recommended Response Actions Based on Hazard Ranking

1.0 Introduction and Approach

Pursuant to an agreement with Chase Lincoln First Bank, N.A. and McCurdy & Company, Inc., The Sear-Brown Group has conducted a survey of friable asbestos-containing building materials (ACBM) within the McCurdy's Midtown facility, East Main Street, Rochester, N.Y. The Sear-Brown Group is a New York State licensed asbestos contractor (#AC-91-0910) and project personnel are New York State certified asbestos building inspectors and management planners.

The purpose of the survey was to: identify areas of the McCurdy Midtown facility where potential friable ACBM may exist; collect samples of suspect friable ACBM for laboratory analysis; markup floor plan drawings showing the locations of sampling locations; (evaluate the condition and quantity of identified friable ACBM) (assess the relative hazard presented by the friable ACBM) and provide a summary report with cost estimates for friable asbestos abatement.

The on-site survey was conducted on June 9, 10, 11, 12 and 15, 1992. Mr. Earl Denton of McCurdy's was the owner's on-site representative who assisted with the survey by providing historical information and access to building areas.

The hazard assessment was conducted using U.S. EPA protocols. Friable ACBM was evaluated both for its condition and its potential for disturbance. A score of 1, 2 or 3 was recorded for a material judged to be in good, fair or poor condition, respectively. A score of 1, 2 or 3 was also recorded for disturbance potential judged to be low, medium or high, respectively. Based on the values of these observations, the relative hazard presented by ACBM was determined using EPA's decision tree (see Figure 1). The relative hazards range from 1 to 7 (i.e. lowest to highest).

The response to ACBM hazards vary depending upon the hazard ranking obtained. Removal of ACBM may be chosen as a permanent solution to asbestos hazards - but it is not required. Encapsulation or enclosure may be done if they effectively seal in asbestos fibers.

As requested, The Sear-Brown Group estimated the costs for removal of the friable ACBM from the facility. Any proposed removal should be prioritized by using the above referenced hazard ranking system. Areas with a hazard rank of 7 should therefore be addressed first and areas with a hazard rank of 1 would be addressed last. Appendix D presents a summary of the EPA recommended response actions by hazard rank.

Estimates of the costs for removal of the friable ACBM were obtained by applying unit cost factors as presented in the 1992 "Means Facilities Cost Data", Seventh Edition, Construction Consultants and Publishers, Kingston, MA.

2.0 Survey Methods

Historical building plans and scale drawings of the current building configuration were obtained and reviewed prior to the site visit. (A visual survey of the building spaces was conducted and the locations, types, conditions, and quantities of suspected friable ACBM were noted) A sampling strategy for the suspect friable ACBM was then devised using the visual survey information.

The physical survey of the building included bulk sampling of the suspect friable ACBM previously identified by the sampling plan. A total of 79 bulk samples were taken from areas that were visually identified to be contiguous with, and/or analogous to, other similar suspect friable ACBM within the structure. Bulk sampling was conducted in accordance with 12 NYCRR 56 and 29 CFR 1910.

Bulk samples were analyzed by Polarized Light Microscopy (PLM) using EPA Method 600/M4-82-020. Analysis of samples was performed by TES Environmental Corporation, Inc., which is certified by the NYSDOH and USEPA to perform such analyses.

3.0 Results and Discussion

The results of laboratory asbestos analysis of bulk samples are summarized in Table 1. The supporting documentation, Asbestos Bulk Sampling Data Sheets and the Laboratory Results, are presented in Appendices A & B, respectively. Marked up floor plans showing bulk sample locations are presented in Appendix C.

General statements about the asbestos content of building systems are difficult for a facility like McCurdy's. Extensive additions, repairs and alterations over a 90 year period have yielded a facility with little that can be reliably predicted.

Asbestos bearing fireproofing is present on structural members and as overspray on decking on all but the subbasement floor in the Northwest (NW) and Southeast (SE) additions. Certain areas of the NW and SE buildings have undergone abatement of fireproofing. These are shown on the drawings furnished by Midtown Holdings.

This friable material contains chrysotile asbestos and has a high potential for disturbance. Fireproofed beams have been enclosed in most areas using sheet rock enclosures or suspended ceilings. Extensive areas of overspray on decking and dislodged fireproofing on the top of suspended ceiling tiles were observed. Asbestos fireproofed areas were calculated to comprise 164,350 total square feet or 33.7% (i.e. 164,350/487,390) of the facility's total square footage.

Piping systems include domestic hot and cold water, chilled water supply and returns, and steam supply and returns. Generally, insulation on pipe joints, elbows, valves and tees contain a hard, trowelled on ACBM (7-24% asbestos).

In many areas, the straight runs of piping contain a soft, non-ACBM thermal insulation such as fiberglass or paper. However, the outer wrap of some of these systems is an ACBM canvas wrap (eg. sample C-SB-5: 10% chrysotile asbestos) or paper (eg. sample C-SB-6: 1% chrysotile asbestos). Pre-formed ACBM thermal insulation was generally observed on older piping systems such as the defunct compressor, steam supply and return lines, and defunct steam lines left in walls and pipe chases. It is difficult to characterize the ACBM content of aircell pipe insulation. For example, of the four samples of chilled water aircell insulation, two were non-ACBM and two were ACBM. The condition of thermal piping insulation varies widely. In some areas, all ACBM has been removed and replaced by fiberglass with PVC covers. In many areas, ACBM piping insulation is in poor condition, having: lost its wrapping; been dislodged; and fallen to the floor. High vibration levels and air currents (especially in pipe chases) adds to the potential for ACBM disturbance in a number of different areas.

Sear-Brown observed and quantified approximately 7,855 linear ft. of ACBM piping insulation. This quantity is not all inclusive. There are piping systems that are hidden from view throughout the facility. These pipes can run above ceilings, within walls and columns and within inaccessible pipe chases. Therefore, without destructive testing, the total footage of ACBM pipe insulation which is hidden from view cannot be determined.

4.0 Removal Cost Estimate

Table 2 presents the results of the hazard assessment for the various friable ACBM and a summary of estimated costs for removal of friable ACBM. The friable ACBM have also been categorized as those needing immediate attention, delayed attention and deferred attention. A list of notes and assumptions used in obtaining estimated costs are provided as an attachment to Table 2.

Our estimate of the probable cost for the complete removal of all observed friable ACBM in the facility is \$4,454,483. Complete removal of friable ACBM with a hazard rank of 6 or 7 has a probable cost of \$4,316,540. Complete removal of friable ACBM with a hazard rank of 4 or 5 has a probable cost of \$104,143. Complete removal of friable ACBM with a hazard rank of 1, 2 or 3 has a probable cost of \$33,797.

Please note that these are estimates only; as such they are useful for preparing preliminary budgets only. Contractor cost estimates vary, and abatement contractors could very well provide bid estimates higher or lower than the costs estimated by Sear-Brown using the historic "Means" data. In particular the current competitive asbestos industry climate may result in lower bids than historic data would suggest.

There is no current regulation requiring removal of ACBM in non-school public buildings. However, if removal of hazardous ACBM is not planned, an effective means of managing the ACBM must be implemented. Repair, enclosure or encapsulation of friable ACBM can effectively contain asbestos fibers if done in conjunction with an effective Operations and Maintenance (O&M) Program.

Tables

Table 1 - Friable Asbestos Containing Building Materials Survey Results - McCurdy's Midtown

<u>Sample No.*</u>	<u>Location</u>	<u>Description</u>	<u>Asbestos Content</u>	
			<u>%**</u>	<u>type***</u>
C-SB-1	Chiller Room	Condensate Pipe Joint	16	C
C-SB-2	Chiller Room	Chilled Water Aircell	ND	NA
C-SB-3	Chiller Room	Chilled water pipe wrap (brown)	ND	NA
C-SB-4	Chiller Room	Chiller pump elbow	15	C
C-SB-5	Chiller Room	Chiller pump wrap (canvas)	10	C
C-SB-6	Chiller Room	Chiller pump wrap (paper)	1	C
C-SB-7	Chiller Room	Compressor valve	16	C
C-SB-8	Chiller Room	Compressor valve wrap (canvas)	ND	NA
C-SB-9	Chiller Room	Compressor pipe (preform)	12	A
C-SB-10	Housekeeping	Duct insulation	20	C
C-SB-11	Carpenter Shop	Domestic hot water joint	15	C
SE-SB-1	Overhead piping	Condensate return joint	25	C
SE-SB-2	Overhead piping	Chilled water supply joint	20	C
SE-SB-3	Overhead piping	Chilled water return joint	15	C
SE-SB-4	Overhead piping	Steam supply tee	18	C
C-B-1	SW Stair Chase	Chilled water supply joint	14	C
C-B-2	SW Stair Chase	Chilled water aircell	ND	NA
C-B-3	SW Stair Chase	Steam supply preform	17	C
C-B-4	Hallway	Duct insulation	12	C
NW-B-1	Budget Store	Steam supply preform	15	C
	(above ceiling)		12	A
NW-B-2	Budget Store	Spline ceiling tile	ND	NA
	(above ceiling)			
M-B-1	Vacant Area	Domestic cold water elbow	ND	NA
M-B-2	Vacant Area	Steam supply preform	21	C
M-B-3	Vacant Area	Steam supply elbow	18/6	C/A
M-B-4	Vacant Area	Paper/Aluminum wrap	ND	NA
M-B-5	Vacant Area	Pipe joint	13	C
M-B-6	Vacant Area	Pipe elbow	18	C
M-B-7	Vacant Area	Pipe aircell	10	C
M-B-8	Vacant Area	Chilled water pipe aircell	16	C
M-B-9	Vacant Area	Chilled water return elbow	9	C
H-B-1	Vacant Area	Steam return pipe aircell	17	C
H-B-2	Mechanical room	Chilled water supply pipe	6	C
E-B-1	Riser C	Pipe elbow	ND	C
E-B-2	Riser C	Steam supply preform	15	C

Table 1 - Friable Asbestos Containing Building Materials Survey Results - McCurdy's Midtown (Cont'd)

<u>Sample No.*</u>	<u>Location</u>	<u>Description</u>	<u>Asbestos Content</u>	
			<u>%**</u>	<u>type***</u>
E-B-3	Riser C	Pipe elbow	7	C
E-B-4	Riser C	Steam return canvas wrap	6	C
E-B-5	Riser C	Ceiling Plaster	ND	NA
SE-B-1	Receiving	Fireproofing on wall	16	C
SE-B-2	Receiving	Fireproofing on ceiling	3	C
SE-B-3	Loading dock	Fireproofing on ceiling	24	C
SE-B-4	Loading dock	Steam supply elbow	18	C
SE-B-5	Loading dock	Steam return elbow	20	C
SE-B-6	Loading dock	Pipe elbow	23	C
M-1-1	Hosiery (Riser B)	Pipe preform	27	C
E-1-1	Stock room	Pipe joint	13	C
	(Riser C)			
E-1-2	Stock room	Chiller water pipe joint	15	C
	(Riser C)			
E-1-3	Stock room	Duct insulation	ND	NA
	(Riser C)			
NW-1-1	Stockroom	Ceiling tile	ND	NA
NW-1-2	Window display	Fireproofing on deck	17	C
M-2-1	Petites Dressing room	Ceiling tile	ND	NA
NW-2-1	Near Stairwell	Fireproofing	15	C
SE-2-1	Hallway to kitchen	Ceiling tile	ND	NA
NW-3-1	Linens Stock Room	Ceiling tile	ND	NA
NW-3-2	Linens Stock Room	Fireproofing	24	C
C-4-1	Stairwell	Firedoor core	15	C
C-4-2	Hallway	Steam riser preform	21/4	C/A
C-4-3	Hallway	Water drain pipe joint	20	C
NW-4-1	Accounting	Fireproofing overspray on deck	25	C
M-4-1	HS&E Backroom	Chilled water return aircell	12	C
M-4-2	HS&E Backroom	Chilled water supply rockwool	ND	NA
M-4-3	HS&E Column	Browncoat	ND	NA

Table 1 - Friable Asbestos Containing Building Materials Survey Results - McCurdy's Midtown (Cont'd)

<u>Sample No. *</u>	<u>Location</u>	<u>Description</u>	<u>Asbestos Content</u>	
			<u>%**</u>	<u>type***</u>
M-4-4	HS&E Column	Scratch coat	ND	NA
M-4-5	HS&E Column	Surface Plaster	ND	NA
SE-4-1	NE corner	Fireproofing on wall	18	C
SE-4-2	SE Stairwell	New fireproofing	5	C
SE-5-1	Utility room	Fireproofing	20	C
C-5-1	Utility access off SW stairwell	Paper/Aluminum/fiber wrap	ND	NA
M-5-1	NW corner	Ceiling plaster	ND	NA
E-5-1	Riser C	Canvas wrap	ND	NA
SE-6-1	Power Room	Fireproofing	14	C
C-6-1	SW Stairwell Chase	Steam line preform	18/12	C/A
C-6-2	SW Stairwell Chase	Pipe elbow	6	C
NW-6-1	Near NW Stairwell	Pipe tee	ND	C
NW-6-2	Records Storage	Fireproofing	17	C
M-6-1	Near Riser A	Ceiling plaster	ND	NA
E-6-1	Riser C	Pipe elbow	22	C
SE-6-2	SE Stairwell Chase	Fireproofing	10	C

Notes: * Sample Numbering scheme: Building - floor - #
NE=Northeast, M=McCurdy's, H=Harris, E=Euclid,
C=Cortland, SE=Southeast

** ND = Not detected

*** C = Chrysotile

A = Amosite

NA = Not applicable

Table 2.

SPACE ID	L, ft	AREAS & M
NW-6 FP+Ls	164	\$0
M-6 RISER A Ls	10	3,819
M-6 RISER B Ls	10	3,819
E-6 RISER C Ls	10	\$0
C-6 STAIR	10	\$0
SE-6	114	\$0
NW-5 FP	164	\$0
M-5 RISER A Ls	10	\$0
M-5 RISER B Ls	10	3,819
E-5 RISER C Ls	10	\$0
C-5 STAIR	10	17,489
SE-5	114	\$0
NW-4 FP	164	\$0
M-4 RISER A Ls	10	3,819
M-4 HS&E BACK ROOM	7	\$0
E-4 RISER C AREA	8	\$0
C-4 STAIR	10	\$0
C-4 ELEV HALL	7	\$0
SE-4	114	\$0
NW-3 FP	164	\$0
M-3 RISER A	10	\$0
M-3 RISER B	10	\$0
E-3 RISER C	10	\$0
C-3 STAIR	10	\$0
SE-3	114	\$0
NW-2 FP	164	\$0
M-2 RISER A	10	\$0
M-2 RISER B	10	\$0
E-2 RISER C	10	\$0
C-2 STAIR AREA	35	\$0
SE-2 FP & ACOUSTIC	114	\$0
NW-1	164	\$0
M-1 RISER A	10	3,839
M-1 RISER B	10	\$0
E-1 RISER C AREA	14	\$0
C-1 STAIR AREA	35	17,193
SE-1 FP AREA 1	114	\$0
SE-1 FP AREA 2	69	\$0
NW-B	164	\$0
M-B RISER A & B AREA	164	\$0
H-B	94	\$0
E-B RISER C AREA	50	\$0
E-B EAST AREA	55	\$0
C-B STAIR AREA	36	\$0
C-B BAKERY AREA	22	\$0
SE-B	114	\$0
M-SB & E-SB	33	\$0
C-SB BOILER ROOMS	15	\$0
C-SB HOUSEKEEPING	32	\$0
C-SB ENGINEERING	50	\$0
C-SB CARPENTER	38	\$0
SE-SB	10	\$0
TOTALS	182720	33,797


KEY:
NW=NORTHWEST BLDG
M=MCCURDY BLDG
H=HARRIS BLDG
FP= FIREPROOFING

Removal Cost Estimate Notes and Assumptions

1. NW-6th includes 10 elbows, and FP but does not include previous abatement area in sq. ft. calculation.
2. M-5 Elbows (Ls) to be removed in a 10'x10'x14' containment area, there are 10 Ls (M-6-1, and M-5-1 not ACBM).
3. H-6.5 no ACBM in Harris.
4. All riser containments local with dimensions of 10'x10'x14'; assume at least 10 Ls.
5. Length is N-S dimension; Width is E-W dimension; Heights are assumed to be 14 ft.
6. Ls worth 1 LF pipe; tees worth 2 LF pipe.
7. "Encapsulated Fireproofing (FP) as defined in Midtown drawings" to be removed.
8. Overspray areas count as fully sprayed for FP removal.
9. "Canvas wrap", "aluminum (Al) on fiberglass (fg)" paper wraps assumed non-ACBM (Note: some canvas wraps are ACBM).
10. Piping not observed in NW-4.
11. E-4 Riser C area. Incomplete FP abatement counted as full FP.
12. Mobilization: \$500 for pipe of low difficulty; \$750 for FP of high difficulty, \$1,000 for complex areas.
13. Executive offices in SE-4 contain no ACBM; Rest of SE-4 ACBM FP.
14. Riser removal areas (especially A) considered separate containment areas.
15. All ceiling tiles are non-ACBM.
16. C-1 stair area (not accessible) similar to C-2 stair area.
17. Reverse F shaped deck area in SE-1 non-ACBM.
18. Cost estimation data from Means. Clean, remove and prep rates as per Means.
19. Pipe removal rates not specified by size; averages were used.
20. Disposal cost: assumed to be \$100/cy.
21. Prep costs include fire retardant poly: 2x cost of non-fire retardant poly.
22. Costs are for removal & disposal only. Many costs not considered such as: reinsulation, air monitoring, insurance, notification fees, etc.

Figures

**FIGURE 1. U.S. EPA ASBESTOS HAZARD ASSESSMENT
DECISION TREE.**



Source: Keyes, D., Price, B. and J. Chesson: "Guidance for Assessing
and Managing Exposure to Asbestos in Buildings."
U.S. EPA. Seventh Draft. 1986

Appendix A
Asbestos Bulk Sampling
Data Sheets

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	chiller supply + return piping

	Unit cooler SB-A → ↓ ↓ ↓ ↓				
SAMPLE #	S -SB-1	C-SB-2	C-SB-3	C-SB-4	C-SB-5
LOCATION #	chiller room	chiller room	chiller room	chiller pump	chiller pump
SAMPLE TYPE	joint, waste condensate	aircell	wrap	elbow mud	canvas wrap
MATERIAL CONDITION	poor	poor	fair	poor	fair
FRIABILITY	high	med	low	high	med

DISTURBANCE POTENTIAL	high	high	med	high	high
Quantity, dia	7 joints	14', 2" dia	150', 10" header	25 joints 10"	150', 10" header


RESULTS	Painted Blue	old canvas wrap	old brown paper wrap, Al backing	mud over glas. orange paint	f. glas under neatz
% ASBESTOS	16	ND	ND	15	10
TYPE ASBESTOS	chry			chry	chry
% OTHER					
TYPE OTHER					

no other unit cooler by old compressor

unit cooler by another pumps
30', 10"

Buildings

CERTIFICATE NO:	
SAMPLED BY: JDT	92-01166
DATE: 6/9/92 pg. 1 of 6	



THE SEAR-BROWN GROUP

Sample #
Bldg - Floor - #
eg. NW-4-2

NW
M
H
E
C
SE

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	C-SB-6	C-SB-7	C-SB-8	C-SB-9	C-SB-10
LOCATION #	Chiller pump (mid)	old compressor	old compressor	old compressor	duct insulation
SAMPLE TYPE	wrap	mud joint	canvas wrap	pre form	mud
MATERIAL CONDITION	good	poor	poor	fair-poor	poor
FRIABILITY	low	high	med	high	high

DISTURBANCE POTENTIAL	high	high	high	med	high
Quantity	50', 10"	12 joints, 10"	40', 10"	150', 4"	40 x 15 x 4

RESULTS	new or rein. paper Al. backing	large valve on compressor	dis-connected steam line?	1/2" thick	
% ASBESTOS	1	16	ND	12	20
TYPE ASBESTOS	Chry	Chry		Amo	Chry
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 6/9/92	pg. 2 of 6



THE
SEABROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	C-SB-11	SE-SB-1	SE-SB-2	SE-SB-3	SE-SB-4
LOCATION #	carpenter shop	in front of rest rooms	in front of rest rooms	in front of rest rooms	in front of rest rooms
SAMPLE TYPE	Down Hst H2O J.	condensate elbow return	chilled water supply elbow	chilled water return line elbow	steam at tee
MATERIAL CONDITION	poor	poor	poor	poor	poor
FRIABILITY	high	high	high	high	high

DISTURBANCE POTENTIAL	low	low	low	low	low
Quantity	see dwg	12 elbows (1 damaged)	5 elbows (1 damaged)	2 elbows	10 tee's

f.g. las runs, small large mud over mud
old canvas wrap fiberglass

RESULTS					
% ASBESTOS	15	17	20	15	18
TYPE ASBESTOS	chry	chry	chry	chry	chry
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 6/9/92 pg. 3 of 6	



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C6
DESCRIPTION	

2nd floor
community
entr.
Ret. air
inlet.
Fireproofed

SAMPLE #	C-4-1	C-4-2	C-4-3	NW-4-1	M-4-1
LOCATION #	SW staircase fire door	hallway outside papers storage	drain on former drink town hall	N. end accounting beam storage	H&E back rm
SAMPLE TYPE	fire door insulation	pre-form pipe insul.	joint	beam overspray	chilled (return?) air cell
MATERIAL CONDITION	good except for penetration	poor	poor	poor	poor
FRIABILITY	medium	high	high	high	high

DISTURBANCE POTENTIAL	high	high	high	high	high
Quantity	3 1/2' x 7' x 1 1/2" (~32 doors)	10' x 2" pipe	1 joint	NW addition entire floor	10' small

steam
riser
pipe buried
in wall,
joint
exposed
on deck +
ceiling tile
in suspended
ceiling
(sample from
deck)

RESULTS					
% ASBESTOS	15	21	20	25	12
TYPE ASBESTOS	chry	chry	chry	chry	chry
% OTHER		4			
TYPE OTHER		Amo			

CERTIFICATE NO:

SAMPLED BY: JOT

DATE: 6/9/92 pg. 4 of 6



THE
SEABROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C#
DESCRIPTION	

SAMPLE #	M-4-2	M-4-3	M-4-4	M-4-5	SE-4-1
LOCATION #	H5+E back room	H5+E pillar/column	H5+E column	H5+E column	northeast corner
SAMPLE TYPE	chilled supply rock wool	brown coat	scratch coat	surface coat	spray-on exterior wall
MATERIAL CONDITION	poor	poor	poor	poor	poor
FRIABILITY	high	high	high	high	high

DISTURBANCE POTENTIAL	high	high	high	high	high
Quantity	8's small	40 s.f.	40 s.f.	40 s.f.	corner area (curved on dry)

no picture L quantity is what is friable now air currents

RESULTS					
% ASBESTOS	ND	ND	ND	ND	18
TYPE ASBESTOS					chry
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/9/92	pg. 5 of 6



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C8
DESCRIPTION	

SAMPLE #	SE-4-2				
LOCATION #	adjacent to southeast stairwell				
SAMPLE TYPE	spray-on from upper wall				
MATERIAL CONDITION	poor				
FRIABILITY	high				

DISTURBANCE POTENTIAL	high				
Quantity	majority of SE bldg				

RESULTS					
% ASBESTOS	5				
TYPE ASBESTOS	chry				
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 4/9/92	pg 6 of 6



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C#
DESCRIPTION	

SAMPLE #	C-B-1	C-B-2	C-B-3	NW-B-1	NW-B-2
LOCATION #	chase outside SW stairwell	chase outside SW stairwell	chase outside SW stairwell	above suspended ceiling	ceiling
SAMPLE TYPE	mud from chilled water	aircell from chilled water	preform on steam line	preform on old steam line	spline tile
MATERIAL CONDITION	poor	poor	poor	good except for tear	fair
FRIABILITY	high	high	high	low except for tear	low except for holes cut in

DISTURBANCE POTENTIAL	high	high	high	low	high
Quantity	5' large pipe (18" o.d.) cross-connect lines to Midtown	16' small pipe (16" o.d.)	20' small (visible here) 1/2 steam, 1/4 dom. water	small length of area 5x width of area 5x	47' x 112' (max. dimensions)

RESULTS					
% ASBESTOS	14	ND	17	15	ND
TYPE ASBESTOS	chry		chry	chry	
% OTHER			10	12	
TYPE OTHER			amo	Amo	

347
30
820+
245

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/10/92	184



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Mid town
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	M-B-1	M-B-2	M-B-3	M-B-4	M-B-5
LOCATION #	unfinished north area	unfinished north area	unfinished north area	unfinished north area	unfinished north end
SAMPLE TYPE	elbow mud on dom water	preform and elbow mud on stream line	elbow mud on elbow off M-B-2	paper alum over fig on pipe	joint mud on M-B-4
MATERIAL CONDITION	fair	fair	poor	fair	poor
FRIABILITY	high	high	high	medium	high

} near Riser A

DISTURBANCE POTENTIAL	high	high	high	high	high
Quantity	28 elbows in 3 parallel pipes	25' large	1 elbow	300+ ft	15+ elbows

w/ paper alum over fig. - 3 @ 75 (dom. water)

8" o.d. runs north-south

falling onto floor

large extend south into across ls. unfinished area

RESULTS					
% ASBESTOS	ND	21	18	ND	13
TYPE ASBESTOS		chry	chry		chry
% OTHER			6		
TYPE OTHER			Amo		

sum
350

sum
20

SAMPLED BY: JOT	CERTIFICATE NO:
DATE: 6/10/92 2534	



THE
SEABROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	M-B-6	M-B-7	M-B-8	M-B-9	H-B-1
LOCATION #	unfinished north end	unfinished north end	unfin. north end Riser A	unfin. north end Riser A	northeast vacant area
SAMPLE TYPE	mud on elbow at riser A	aircell on defect small pipe	paper aircell on chiller drain	mud on chiller drain	aircell on condensate drain
MATERIAL CONDITION	poor	poor	locally poor	locally poor	poor
FRIABILITY	high	high	low	high	high

DISTURBANCE POTENTIAL	high	high	high	high	high
Quantity	7 elbows large	10' small	<10' small	5 elbows 5 joints	80' small

RESULTS	<p>highly disturbed at riser</p> <p>falling on floor Additional 20' suspect AC mud under fig. wrap</p>				
% ASBESTOS	18	10	16	9	17
TYPE ASBESTOS	Chry	Chry	Chry	Chry	Chry
% OTHER					
TYPE OTHER					

SAMPLED BY:	JDT	CERTIFICATE NO:
DATE:	6/10/92	3074



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C6
DESCRIPTION	

SAMPLE #	H-B-2	E-B-1	E-B-2	E-B-3	
LOCATION #	chill water supply on at River	at River	se. corner Elm St bldg	near River	
SAMPLE TYPE	mud over paper on floor	mud on elbow - defunct pipe	preform on stream pipe	mud on elbow	
MATERIAL CONDITION	poor	poor	poor	poor	
FRIABILITY	high	high	high	high	

DISTURBANCE POTENTIAL	high	high	high	high	
Quantity	5 elbows	2 elbows	4 ft. large	4 elbows	

RESULTS	<p>9 elbows in storage area pipe is canvas on fug. steam main is canvas on pre-form small</p>				
% ASBESTOS	6	ND	15		
TYPE ASBESTOS	chry		chry		
% OTHER			10		
TYPE OTHER			Amo		

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/10/92	484

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	E-B-3	E-B-4	E-B-5	SE-B-1	SE-B-2
LOCATION #	near Riser C	steam main + condensate near Riser C	storage room at Riser C	Receiving N.E. corner	Receiving W.E. corner
SAMPLE TYPE	mud on elbow	canvas on paper on cond. return	white ceiling plaster	spray-on from upper wall	spray-on from beams + ceiling
MATERIAL CONDITION	poor	fair	poor	fair	fair
FRIABILITY	high	medium	high	high	high

DISTURBANCE POTENTIAL	high	high	high	moderate	high
Quantity	4 elbows	45' small	50'x50' room	3'x50'	receiving area ceiling

pipe is cloth on top - 5' small plus 25' on steam main on floor looks old 50'x80'

RESULTS					
% ASBESTOS	7	6	ND	16	3
TYPE ASBESTOS	chry	chry		chry	chry
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/11/92	1574

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	SE-B-3	SE-B-4	SE-B-5	SE-B-6	C-B-4
LOCATION #	NE corner loading dock	NE area loading dock	NE area loading dock	NW corner loading dock	hallway to loading dock
SAMPLE TYPE	ceiling spray-on	mud elbow on large steam supply	mud elbow on typical steam return	mud elbow typical	white plaster
MATERIAL CONDITION	poor	poor	poor	poor	fair (cracks)
FRIABILITY	high	high	high	high	moderate

DISTURBANCE POTENTIAL	high at access points	high	high	high	high
Quantity		~50 elbows	~25 elbows	10 damaged elbows	120 s.f.

RESULTS	all covered, w/access panels looks old	~20% are damaged Total ~ 50 elbows ~75% system	~20% are damaged Total ~25 elbows	very poor condition. Plus 30 good cond. elbows	
% ASBESTOS	24	18	20	23	12
TYPE ASBESTOS	chry	chry	chry	chry	chry
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/11/92	2 of 4



THE
SEABROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	M-1-1	E-1-1	E-1-2	E-1-3	NW-1-1
LOCATION #	Riser B at 1st floor hallway	Riser C in stock rm.	Riser C in stock rm.	Riser C in stock rm.	nw corner stockroom
SAMPLE TYPE	preform on pipe	mud on joint - drain pipe	mud on joint - sm. chiller w. pipe	dust insul. canvas on fig.	ceiling tile's plie
MATERIAL CONDITION	poor	poor	poor	poor	good
FRIABILITY	high	high	high	high	moderate

DISTURBANCE POTENTIAL	high	high	high	high	low
Quantity	20 ft this floor -	~2 elbows	~15 elbows	~90 s.f.	nw Addition

appears to go all the way up "85% magnesite" strong air currents

RESULTS	appears to go all the way up "85% magnesite"				
% ASBESTOS	27	13	15	ND	ND
TYPE ASBESTOS	Chry	Chry	Chry		
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/11/92	3 of 4



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	NW-1-2	6-3-5			
LOCATION #	NW display window	chase N of SW stairwell			
SAMPLE TYPE	spray-on ceiling deck beam	canvas over brown paper			
MATERIAL CONDITION	poor	good			
FRIABILITY	high	medium			

DISTURBANCE POTENTIAL	high	high air flow			
Quantity	deck of NW stairs	height of bldg small			

return air plenum
see 6/1/2

RESULTS					
% ASBESTOS	17				
TYPE ASBESTOS	Chry				
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/1/92 4 of 4	

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	SE-6-1	C-6-1	C-6-2	NW-6-1	NW-6-2
LOCATION #	Power Room	sw stairwell into access	sw stairwell into access	main ceiling, i.e. off NW stairwell	records storage area in Depos. Opns
SAMPLE TYPE	spray-on from beam	pre-form downspout covered on defunct line	mud bed elbow	mud from tee, etc. of main stair	spray-on from beams + deck
MATERIAL CONDITION	poor	poor	fair	1 poor 9 good	poor
FRIABILITY	high	high	high	high	high

DISTURBANCE POTENTIAL	high	high	instairwell - medium in chase - high	high	high
Quantity	Beams in SE Addition	10 ft large	4 elbows	10 elbows	at but center of NW addition (plan) portion floor
RESULTS	* return air plenum. 7ch falling on c.t. led. Only on beams	probably defunct steam	2 elbows in stairwell are damaged	high air flow *	high air flow *

% ASBESTOS	14	18	6	ND	17
TYPE ASBESTOS	C	C	C		C
% OTHER		12			
TYPE OTHER		A			

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 6/12/92	1 of 3



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	M-5-1	E-5-1	C-B-5		
LOCATION #	ceiling near NW corner McCurdy's bldg	Riser C	chase N of SW stairwell		
SAMPLE TYPE	ceiling plaster	canvas on fig.	canvas over brown paper		
MATERIAL CONDITION	good	fair	good		
FRIABILITY	moderate	moderate	medium		

DISTURBANCE POTENTIAL	high	moderate	high (airflow)		
Quantity	McCurdy's bldg (4 others) high air flow x	small - 5' large - 15' (keeps going)	height of bldg - main pipe		

RESULTS					
% ASBESTOS	ND	ND	16		
TYPE ASBESTOS			Chry		
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 6/12/92	3 of 3



THE
SEABROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	M-6-1	E-6-1	SE-6-2	SE-5-1	C-5-1
LOCATION #	in ceiling next to Riser A	Riser C	riser next to S.E. stairwell	utility room next to elevator	utility access off SW stairwell
SAMPLE TYPE	ceiling plaster	mud elbow	spray-on support structure	spray-on from beam overspray	paper aluminum on fiberglass
MATERIAL CONDITION	poor	poor	poor	poor	good
FRIABILITY	high	high	high	high	moderate

DISTURBANCE POTENTIAL	high	low	high	moderate here	high
Quantity	McCurdy's Bldg	1 elbow 1 tee	1 elbow 1 tee 3 s.f. thick		

RESULTS	over suspended ceiling high air * flow - return air plenum	ducted return	strong * air current		air flow * on chilled water - large AFU!
% ASBESTOS	ND	22	10	20	ND
TYPE ASBESTOS		C	C	C	
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 6/12/92	293

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	M-2-1	NW-2-1	SE-2-1	NW-3-1	NW-3-2
LOCATION #	Petite's dressing room	outside NW stairwell	hallway into kitchen	linens stockroom	linens stockroom
SAMPLE TYPE	spline ceiling tile	ceiling spray-on	spline ceiling tile	spline ceiling tile	spray-on from beam
MATERIAL CONDITION	good	poor	poor	good	poor
FRIABILITY	high	high	high	high	high

DISTURBANCE POTENTIAL	medium	high	high	high	high
Quantity	Harris, McC NW + Elms + buildings	NW Addition	~12 s.f. (another 30 s.f. stock)	NW bldg except rooms	NW bldg
RESULTS	condition locally poor	airflow - returns not ducted *	in office at Riser C) cut, holes *	breezy *	high air movement *

% ASBESTOS	ND	15	ND	ND	24
TYPE ASBESTOS		C		M	C
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JDT	
DATE: 6/15/92 1 of 2	



THE
SEAR-BROWN
GROUP

ASBESTOS BULK SAMPLING DATA SHEET

PROJECT NAME	McCurdy's Midtown
PROJECT #	8664C
DESCRIPTION	

SAMPLE #	H-3-1				
LOCATION #	weight watcher entrance				
SAMPLE TYPE	spine during tile				
MATERIAL CONDITION	good				
FRIABILITY	medium				

DISTURBANCE POTENTIAL	medium				
Quantity	Harris Bb incl. above new ceiling in w/ watcher				

RESULTS					
% ASBESTOS					
TYPE ASBESTOS					
% OTHER					
TYPE OTHER					

CERTIFICATE NO:	
SAMPLED BY: JOT	
DATE: 6/15/92 2 of 2	

Appendix B
Laboratory Results



POLARIZED LIGHT WITH DISPERSION STAINING
BULK SAMPLE ANALYSIS

CLIENT: THE SEAR-BROWN GROUP
85 Metro Park
Rochester, NY 14623
ATTN: Mr. Jeff Tallon

PROJECT:

<u>SAMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
✓#C-4-1	92B-299-1	N/A	Homogeneous, Gray	Chrysotile	15%
✓#C-4-2	92B-299-2	N/A	Homogeneous, White	Chrysotile Amosite	21% 04%
✓#C-4-3	92B-299-3	N/A	Homogeneous, Gray	Chrysotile	20%
✓#NW-4-1	92B-299-4	N/A	Homogeneous, Gray	Chrysotile	25%
✓#M-4-1	92B-299-5	N/A	Homogeneous, Gray	Chrysotile	12%
✓#C-SB-6	92B-299-6	N/A	Homogeneous, Gray	Chrysotile	01%
✓#C-SB-7	92B-299-7	N/A	Homogeneous, Gray	Chrysotile	16%
✓#C-SB-8	92B-299-8	N/A	Homogeneous, Brown, Gray	Non-Detected	
✓#C-SB-9	92B-299-9	N/A	Homogeneous, Gray	Amosite	12%
✓#C-SB-10	92B-299-10	N/A	Homogeneous, Gray	Chrysotile	20%
✓#SE-4-2	92B-299-11	N/A	Homogeneous, Beige	Chrysotile	05%
✓#M-4-2	92B-299-12	N/A	Homogeneous, Tan	Non-Detected	
✓#M-4-3	92B-299-13	N/A	Homogeneous, Gray	Non-Detected	
✓#M-4-4	92B-299-14	N/A	Homogeneous, White	Non-Detected	
✓#M-4-5	92B-299-15	N/A	Homogeneous, White	Non-Detected	
✓#SE-4-1	92B-299-16	N/A	Homogeneous, White	Chrysotile	18%
✓#C-SB-11	92B-299-17	N/A	Homogeneous, Gray	Chrysotile	15%

PAGE 2

<u>SAMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
/#SE-SB-1	92B-299-18	N/A	Homogeneous, Beige	Chrysotile	17%
/#SE-SB-2	92B-299-19	N/A	Homogeneous, Beige	Chrysotile	20%
/#SE-SB-3	92B-299-20	N/A	Homogeneous, Beige	Chrysotile	15%
/#SE-SB-4	92B-299-21	N/A	Homogeneous, Beige	Chrysotile	18%
/#C-SB-1	92B-299-22	N/A	Homogeneous, Beige	Chrysotile	16%
/#C-SB-2	92B-299-23	N/A	Homogeneous, Brown	Non-Detected	
/#C-SB-3	92B-299-24	N/A	Homogeneous, Brown	Non-Detected	
/#C-SB-4	92B-299-25	N/A	Homogeneous, Gray	Chrysotile	15%
/#C-SB-5	92B-299-26	N/A	Homogeneous, Gray	Chrysotile	10%

Sample collection not performed by T.E.S., Corp.Analyst: M. Fleming

Date: _____

Laboratory Director: _____

Date Recd: June 10, 1992

ANALYTICAL REFERENCE: Sample evaluations have been accomplished in accordance with the EP "Interim Method for the Determination of Asbestos in Bulk Insulation Sample"--EPA publication 600/M4-82-020 December 1982.

FURTHER REFERENCE: "Bulk Analysis For Asbestos Content: Evaluation of the Tentative Method"--EPA publication EPA-6--/4-82-021 April 1982.



POLARIZED LIGHT WITH DISPERSION STAINING
BULK SAMPLE ANALYSIS

CLIENT: THE SEAR-BROWN GROUP
85 Metro Park
Rochester, NY 14623
ATTN: Mr. Jeff Tallon

PROJECT:

<u>SAMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
#E-B-3	92B-305-1	N/A	Homogeneous, White	Chrysotile	07%
#E-B-4	92B-305-2	N/A	Homogeneous, Tan, White	Chrysotile	06%
#E-B-5	92B-305-3	N/A	Homogeneous, White	Non-Detected	
#SE-B-1	92B-305-4	N/A	Homogeneous, Gray	Chrysotile	16%
#SE-B-2	92B-305-5	N/A	Homogeneous, Beige	Chrysotile	03%
#SE-B-3	92B-305-6	N/A	Homogeneous, Gray	Chrysotile	24%
#SE-B-4	92B-305-7	N/A	Homogeneous, Gray	Chrysotile	18%
#SE-B-5	92B-305-8	N/A	Homogeneous, Gray	Chrysotile	20%
#SE-B-6	92B-305-9	N/A	Homogeneous, Beige	Chrysotile	23%
#C-B-4	92B-305-10	N/A	Homogeneous, Gray	Chrysotile	12%
#C-B-5	92B-305-11	N/A	Homogeneous, Gray, Tan	Chrysotile	16%
#M-1-1	92B-305-12	N/A	Homogeneous, Gray	Chrysotile	27%
#E-1-1	92B-305-13	N/A	Homogeneous, Beige	Chrysotile	13%
#E-1-2	92B-305-14	N/A	Homogeneous, Gray	Chrysotile	15%
#E-1-3	92B-305-15	N/A	Homogeneous, Black	Non-Detected	
#NW-1-1	92B-305-16	N/A	Homogeneous, Gray	Non-Detected	
#NW-1-2	92B-305-17	N/A	Homogeneous, Gray	Chrysotile	17%

Sample collection not performed by T.E.S., Corp.

Analyst: M. Fleming

Date: _____

Laboratory Director: _____

Date Recd: June 12, 1992

ANALYTICAL REFERENCE: Sample evaluations have been accomplished in accordance with the E1
"Interim Method for the Determination of Asbestos in Bulk Insulation Sample"--EPA publicati
600/M4-82-020 December 1982.

FURTHER REFERENCE: "Bulk Analysis For Asbestos Content: Evaluation of the Tentati
Method"--EPA publication EPA-6--/4-82-021 April 1982.



POLARIZED LIGHT WITH DISPERSION STAINING
BULK SAMPLE ANALYSIS

CLIENT: THE SEAR-BROWN GROUP
85 Metro Park
Rochester, NY 14623
ATTN: Mr. Jeff Tallon

PROJECT:

<u>SAMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
#C-B-1	92B-306-1	N/A	Homogeneous, Beige	Chrysotile	14%
#C-B-2	92B-306-2	N/A	Homogeneous, Brown	Non-Detected	
#C-B-3	92B-306-3	N/A	Homogeneous, White	Chrysotile Amosite	17% 10%
#NW-B-1	92B-306-4	N/A	Homogeneous, White	Chrysotile Amosite	15% 12%
#NW-B-2	92B-306-5	N/A	Homogeneous, Gray	Non-Detected	
#M-B-1	92B-306-6	N/A	Homogeneous, Gray	Non-Detected	
#M-B-2	92B-306-7	N/A	Homogeneous, White	Chrysotile	21%
#M-B-3	92B-306-8	N/A	Homogeneous, Gray	Chrysotile Amosite	18% 06%
#M-B-4	92B-306-9	N/A	Homogeneous, Brown	Non-Detected	
#M-B-5	92B-306-10	N/A	Homogeneous, Gray	Chrysotile	13%
#M-B-6	92B-306-11	N/A	Homogeneous, Gray	Chrysotile	18%
#M-B-7	92B-306-12	N/A	Homogeneous, Brown	Chrysotile	10%
#M-B-8	92B-306-13	N/A	Homogeneous, Brown, Gray	Chrysotile	16%
#M-B-9	92B-306-14	N/A	Homogeneous, Gray	Chrysotile	09%
#H-B-1	92B-306-15	N/A	Homogeneous, Gray	Chrysotile	17%

1080 University Avenue, Rochester, New York 14607

(716)473-3660

Fax(716)473-3775

1-800-952-5952

<u>SAMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
#H-B-2	92B-306-16	N/A	Homogeneous, Gray	Chrysotile	06%
#E-B-1	92B-306-17	N/A	Homogeneous, Gray	Non-Detected	
#E-B-2	92B-306-18	N/A	Homogeneous, Gray	Chrysotile Amosite	15% 10%

61 Sample collection not performed by T.E.S., Corp.

Analyst: M. Fleming

Date: _____

Laboratory Director: _____

Date Recd: June 12, 1992

ANALYTICAL REFERENCE: Sample evaluations have been accomplished in accordance with the EF "Interim Method for the Determination of Asbestos in Bulk Insulation Sample"--EPA publicatio 600/M4-82-020 December 1982.

FURTHER REFERENCE: "Bulk Analysis For Asbestos Content: Evaluation of the Tentativ Method"--EPA publication EPA-6--/4-82-021 April 1982.



POLARIZED LIGHT WITH DISPERSION STAINING
BULK SAMPLE ANALYSIS

CLIENT: THE SEAR-BROWN GROUP
85 Metro Park
Rochester, NY 14623
ATTN: Mr. Jeff Tallon

PROJECT:

<u>SAMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
#M-5-1	92B-312-1	Plaster	Homogeneous, Gray	Non-Detected	
#E-5-1	92B-312-2	N/A	Homogeneous, Tan	Non-Detected	
#C-B-5	92B-312-3	N/A	Homogeneous, Gray, Tan	Chrysotile	25%
#M-6-1	92B-312-4	Plaster	Homogeneous, Gray	Non-Detected	
6-1	92B-312-5	N/A	Homogeneous, Gray	Chrysotile	22%
#SE-6-2	92B-312-6	N/A	Homogeneous, Beige	Chrysotile	10%
#SE-5-1	92B-312-7	N/A	Homogeneous, Gray	Chrysotile	20%
#C-5-1	92B-312-8	N/A	Homogeneous, Tan	Non-Detected	
#SE-6-1	92B-312-9	N/A	Homogeneous, Gray	Chrysotile	14%
#C-6-1	92B-312-10	N/A	Homogeneous, White	Chrysotile Amosite	18% 12%
#C-6-2	92B-312-11	N/A	Homogeneous, Gray	Chrysotile	06%
#NW-6-1	92B-312-12	N/A	Homogeneous, Gray	Non-Detected	
#NW-6-2	92B-312-13	N/A	Homogeneous, White	Chrysotile	17%
#M-2-1	92B-312-14	N/A	Homogeneous, Gray	Non-Detected	
#NW-2-1	92B-312-15	N/A	Homogeneous, Gray	Chrysotile	15%
#SE-2-1	92B-312-16	N/A	Homogeneous, Beige	Non-Detected	

<u>AMPLE ID</u>	<u>TES #</u>	<u>SAMPLE LOCATION</u>	<u>SAMPLE DESCRIPTION</u>	<u>ASBESTOS TYPE</u>	<u>PERCENT ASBESTOS</u>
#NW-3-1	92B-312-17	N/A	Homogeneous, Gray	Non-Detected	
#NW-3-2	92B-312-18	N/A	Homogeneous, Gray	Chrysotile	

Sample collection not performed by T.E.S., Corp.

Analyst: M. Fleming

Date: _____

Laboratory Director: _____

Date Recd: June 16, 1992

ANALYTICAL REFERENCE: Sample evaluations have been accomplished in accordance with the EPA "Interim Method for the Determination of Asbestos in Bulk Insulation Sample"--EPA publication 00/M4-82-020 December 1982.

FURTHER REFERENCE: "Bulk Analysis For Asbestos Content: Evaluation of the Tentative method"--EPA publication EPA-6--/4-82-021 April 1982.

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: C-4-1

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-4-2

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-4-3

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: NW-4-1

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: M-4-1

BULK _____ SWIPE _____ QUANTITY _____

SAMPLES COLLECTED BY: Jeff Jaffe

DATE: 6/9/92

DELIVERED BY: KOD

DATE: 6/10/92

RECEIVED BY: RS

DATE: 6/10/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: C-SB-6

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-7

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-8

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-9

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-10

BULK _____ SWIPE _____ QUANTITY _____

SAMPLES COLLECTED BY: *Jeff J. Miller*

DATE: 6/9/92

DELIVERED BY: *KOD*

DATE: 6/10/92

RECEIVED BY: *ss*

DATE: 6/10/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: SE-4-2

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: _____

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: _____

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: _____

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: _____

BULK _____ SWIPE _____ QUANTITY _____

SAMPLES COLLECTED BY: Jeff Joller

DATE: 6/9/92

DELIVERED BY: RJD

DATE: 6/10/92

RECEIVED BY: ss

DATE: 6/10/92

TOTAL # OF SAMPLES 1

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: M-4-2

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: M-4-3

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: M-4-4

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: M-4-5

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: SE-4-1

BULK _____ SWIPE _____ QUANTITY _____

SAMPLES COLLECTED BY: JM Jolly

DATE: 6/9/92

DELIVERED BY: ROD

DATE: 6/10/92

RECEIVED BY: AS

DATE: 6/10/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: C-SB-11

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: SE-SB-1

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: SE-SB-2

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: SE-SB-3

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: SE-SB-4

BULK _____ SWIPE _____ QUANTITY _____

SAMPLES COLLECTED BY: [Signature]

DATE: 6/9/92

DELIVERED BY: [Signature]

DATE: 6/10/92

RECEIVED BY: [Signature]

DATE: 6/10/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: C-SB-1

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-2

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-3

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-4

BULK _____ SWIPE _____ QUANTITY _____

LOCATION: C-SB-5

BULK _____ SWIPE _____ QUANTITY _____

SAMPLES COLLECTED BY: [Signature]

DATE: 6/9/92

DELIVERED BY: [Signature]

DATE: 6/10/92

RECEIVED BY: [Signature]

DATE: 6/10/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP #

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: E-B-3

BULK ✓ SWIPE QUANTITY

LOCATION: E-B-4

BULK ✓ SWIPE QUANTITY

LOCATION: E-B-5

BULK ✓ SWIPE QUANTITY

LOCATION: SE-B-1

BULK ✓ SWIPE QUANTITY

LOCATION: SE-B-2

BULK ✓ SWIPE QUANTITY

SAMPLES COLLECTED BY: *[Signature]*

DATE: 6/11/92

DELIVERED BY: *[Signature]*

DATE: 6-12-92

RECEIVED BY: *[Signature]*

DATE: 6/12

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: SE-B-3

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: SE-B-4

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: SE-B-5

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: SE-B-6

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: C-B-4

BULK ☒ SWIPE ☐ QUANTITY

SAMPLES COLLECTED BY: Jeff Talb

DATE: 6/18/92

DELIVERED BY: _____

DATE: _____

RECEIVED BY: AS

DATE: 6/12

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: C-8-5

BULK ✓ SWIPE QUANTITY

LOCATION: M-1-1

BULK ✓ SWIPE QUANTITY

LOCATION: E-1-1

BULK ✓ SWIPE QUANTITY

LOCATION: E-1-2

BULK ✓ SWIPE QUANTITY

LOCATION: E-1-3

BULK ✓ SWIPE QUANTITY

SAMPLES COLLECTED BY: *Jeff Teller*

DATE: 6/18/92

DELIVERED BY:

DATE:

RECEIVED BY: *AS*

DATE: 6/12

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

Jeff Gallen

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: C-B-1

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: C-B-2

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: C-B-3

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: NW-B-1

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: NW-B-2

BULK ☒ SWIPE ☐ QUANTITY

SAMPLES COLLECTED BY: *Jeff Gallen*

DATE: 6/10/92

DELIVERED BY: *D. Collier*

DATE: 6-12-92

RECEIVED BY: *ss*

DATE: 6-12-91

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY
BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: M-B-1

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: M-B-2

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: M-B-3

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: M-B-4

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: M-B-5

BULK ☒ SWIPE ☐ QUANTITY

SAMPLES COLLECTED BY: Jeff Teller

DATE: 6/10/92

DELIVERED BY: _____

DATE: _____

RECEIVED BY: AS

DATE: 6/12/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: m - B - 6

BULK ✓ SWIPE QUANTITY

LOCATION: m - B - 7

BULK ✓ SWIPE QUANTITY

LOCATION: m - B - 8

BULK ✓ SWIPE QUANTITY

LOCATION: m - B - 9

BULK ✓ SWIPE QUANTITY

LOCATION: H - B - 1

BULK ✓ SWIPE QUANTITY

SAMPLES COLLECTED BY: Jeff Teller

DATE: 6/10/92

DELIVERED BY:

DATE:

RECEIVED BY: AS

DATE: 6/12/92

TOTAL # OF SAMPLES 5

CHAIN OF CUSTODY
BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: H-B-2

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: E-B-1

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: E-B-2

BULK ☒ SWIPE ☐ QUANTITY

LOCATION: _____

BULK ☐ SWIPE ☐ QUANTITY

LOCATION: _____

BULK ☐ SWIPE ☐ QUANTITY

SAMPLES COLLECTED BY: *[Signature]* DATE: 6/10/92

DELIVERED BY: _____ DATE: _____

RECEIVED BY: *[Signature]* DATE: 6/12/92

TOTAL # OF SAMPLES 3

CHAIN OF CUSTODY

#8664C

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: SE-6-1

BULK ✓

SWIPE

QUANTITY 1

LOCATION: C-6-1

BULK ✓

SWIPE

QUANTITY 1

LOCATION: C-6-2

BULK ✓

SWIPE

QUANTITY 1

LOCATION: NW-6-1

BULK ✓

SWIPE

QUANTITY 1

LOCATION: NW-6-2

BULK ✓

SWIPE

QUANTITY 1

SAMPLES COLLECTED BY: J. J. Teller

DATE: 6/12/92

DELIVERED BY: W. Danc

DATE: 6/16/92

RECEIVED BY: AS

DATE: 41

TOTAL # OF SAMPLES 5

#8664C

CHAIN OF CUSTODYBULK/SWIPE SAMPLESCONTRACTOR/CLIENT: THE SEAR-BROWN GROUPADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623PHONE NUMBER: (716) 475-1440FAX NUMBER: (716) 272-1814LOCATION: M-6-1BULK ✓SWIPE QUANTITY 1LOCATION: E-6-1BULK ✓SWIPE QUANTITY 1LOCATION: SE-6-2BULK ✓SWIPE QUANTITY 1LOCATION: SE-5-1BULK ✓SWIPE QUANTITY 1LOCATION: C-5-1BULK ✓SWIPE QUANTITY 1

SAMPLES COLLECTED BY:

J. M. MillerDATE: 6/12/92

DELIVERED BY:

J. C. DavisDATE: 6/16/92

RECEIVED BY:

ASDATE: 6TOTAL # OF SAMPLES 5

#8664C

CHAIN OF CUSTODY
BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: M-5-1

BULK ☒ SWIPE ☐ QUANTITY 1

LOCATION: E-5-1

BULK ☒ QUANTITY 1

LOCATION: C-B-5

BULK ☒ QUANTITY 1

LOCATION: _____

BULK ☐ QUANTITY _____

LOCATION: _____

BULK ☐ QUANTITY _____

SAMPLES COLLECTED BY: _____

DATE: 6/12/92

DELIVERED BY: H. Davis

DATE: 6/16/92

RECEIVED BY: RS

DATE: "

TOTAL # OF SAMPLES 3

CHAIN OF CUSTODY

BULK/SWIPE SAMPLES

CONTRACTOR/CLIENT: THE SEAR-BROWN GROUP

8664C

ADDRESS: 85 METRO PARK
ROCHESTER, N.Y. 14623

PHONE NUMBER: (716) 475-1440

FAX NUMBER: (716) 272-1814

LOCATION: M-2-1

BULK ☒ SWIPE ☐ QUANTITY 1

LOCATION: NW-2-1

BULK ☒ SWIPE ☐ QUANTITY 1

LOCATION: SE-2-1

BULK ☒ SWIPE ☐ QUANTITY 1

LOCATION: NW-3-1

BULK ☒ SWIPE ☐ QUANTITY 1

LOCATION: NW-3-2

BULK ☒ SWIPE ☐ QUANTITY 1

SAMPLES COLLECTED BY: J. J. Puller

DATE: 6/15/92

DELIVERED BY: [Signature]

DATE: 6/15/92


RECEIVED BY: SS

DATE: 11

TOTAL # OF SAMPLES 5

Appendix C


Floor Plans



McCurdy Basement ACM Plan		
SCALE: AS SHOWN	DRAWN: sdd	
DATE: 8/8/95	DWG #: A-0	




	ENCAPSULATED
	EXIST
	NONE



2/96 Revised and updated plan		MCCURDY FIRST FLOOR ACM PLAN	
		SCALE: AS SHOWN	DRAWN KP
		DATE: 1/18/96	DWG #:



- REMOVE
- ENCAPSULATED
- CURTS
- MGS



REMOVED

ENCAPSULATED

EXIST

NOTE

McCURDY SECOND FLOOR ACM PLAN

SCALE: AS SHOWN


DATE: 8/7/95

DRAWN: sdd


DWG #: A-2

8/95 Revised and updated plan


0 5 10 15 20



8/15	Revised and updated plan	mb	McCURDY THIRD FLOOR ACM PLAN
			SCALE: AS SHOWN
			DATE: 8/7/95
			DRAWN: SGD
			DWG #: A-




UNCONSOLIDATED	EXIST	REMOVE



ENCAPSULATED
 EXISTS
 NONE




McCURDY FOURTH FLOOR ACM PLAN
 SCALE: AS SHOWN DRAWN: sdd
 DATE: 8/8/95 DWG #: A-



ENCAPSULATED
INTACT
NONE



McCURDY FIFTH FLOOR ACM PLAN		
SCALE: AS SHOWN	KP	
MAY 96	DWG #:	A-5



McCURDY SIXTH FLOOR ACM PLAN		
SCALE: AS SHOWN	KP	
MAY 96	DWG #:	A-6



	ENCAPSULATED
	EXISTS
	NONE

Appendix D

**USEPA Recommended Response Actions
Based on Hazard Ranking**

USEPA RECOMMENDED RESPONSE ACTIONS BASED ON HAZARD RANKING

Hazard Rank	Removal Priority	AHERA Categories	Response Actions Required by AHERA
7	1	Significantly Damaged	Evacuate or isolate the area if needed. Remove the ACBM (or enclose or encapsulate if sufficient to contain fibers). Repair of thermal system insulation is allowed if feasible and safe. O&M required for all friable ACBM.
6	2	Damaged + Potential for Significant Damage	Evacuate or isolate the area if needed. Remove, enclose, encapsulate, or repair to correct damage. Take steps to reduce potential for disturbance. O&M required for all friable ACBM.
5	3	Damaged + Potential for Damage	Remove, enclose, encapsulate, or repair to correct damage. O&M required for all friable ACBM.
4	4	Damaged	Same as hazard rank 5
3	5	Potential for Significant Damage	Evacuate or isolate the area if needed. Take steps to reduce potential for disturbance. O&M required for all friable ACBM.
2	6	Potential for Damage	O&M required for all friable ACBM.
1	7	No Problem	O&M required for all friable ACBM, but measures need not be as extensive as above.

Note: AHERA does not account for combinations of current and potential damage (i.e., hazard ranks #5 and 6). The response actions shown are combinations of those required for each condition.

Source: Keyes, D., B. Price and J. Chesson: "Guidance for Assessing and Managing Exposure to Asbestos in Buildings". USEPA. Seventh Draft. 1986