


**Park Drive Realignment Impacts:**

1. Removal of 4 mature oak trees (all with a caliper greater than 24")
2. Removal of approximately 15 to 20 mid growth trees (all with a caliper greater than 8")
3. Removal of all shrub/ shrub growth within the area of impact in order to perform grading for drive realignment.



**TYLIN**INTERNATIONAL

**Brooks Landing Phase II Public Improvements Realigned drive connection impacts**